

FS-5000/8000 Modification of PA and COUP Boards

	Necessary Parts (See table below.)	Refer to page:
1. Tuning error on MF band -----	Ⓐ -----	2
2. Burned-out COUP board ----- (on MF band)	Ⓑ -----	4
3. Burned-out PA board over 22MHz ----- (continuous transmission for about 2 minutes at full power)	Ⓒ -----	13

Table

Necessary Parts	Type	Code No.	Required for:
* ROM (U3)	0550132102	005-927-430	Ⓐ (on COUP Board)
* Silicone Sealant	KE-348T	000-801-041	
* Resistors (R5/R8, 2 pcs.)	ERD-25PJ472 4.7K, 1/4W	000-330-373	
Silicone Sealant	KE-348T	000-801-041	Ⓑ Installation of shunt capacitor on DUMMY LOAD PCB.
DUMMY LOAD PCB	OP05-34	005-925-830	
Antenna Capacitor (ceramic, for shunting)	DC-40, 50 pF or DC-40, 100 pF	000-258-695 000-258-696	
Crimp-on lug (M4), Lug (M4), SWs (M4), Nut (M4), Screw M4 × 12, some wires 1.25 sq.			Ⓒ Installation of arrester fixing metal on AN- TENNA COUPLER.
* Arrester Fixing Metal	05-039-6314	100-134-990	
* Ground Cable (with lugs at both ends)	—	—	
* Cable Clamp (3 pcs.)	CK-05H	000-570-247	
M4 Nut, Screw M4 × 25			Ⓒ (on PA Board) delivered as an assemb- ly
* Transformer (T4)	5T814	000-122-137	
* Coaxial Cable	05S0689-0	000-119-452	
* Transformer Clamp	05-039-6124	100-144-010	
* Copper Strap (2 pcs.)	—	—	

(*): Free of charge

1. Tuning error on MF band (Modification on COUP board)

Factory-modified Units:

FS-5000	FS-8000
2508-0095, 0096, 0105 and after	2522-0013 and after

Modifications:

- ① **Replacement of ROM. (05501-32-101 → 05501-32-102)**
Refer to Fig. 1 for the location.
- ② **Reducing number of turns of L8 and L9 by one turn.**
(L8: 12.5T → 11.5T, L9: 19.5T → 18.5T)
See the next page.
- ③ **Change of resistance values of R5 and R8.**
(10K ohms → 3.3 K ohms)
Refer to Fig. 1 for the locations.

NOTE: If there is a black label (●) at the bottom of the Antenna Coupler (near the earth clamp), the above modifications have been already done at factory.





Fig. 1 COUP Board

Reducing number of turns (L8/L9)



Procedure

1. Solder **(a)** to shortcircuit the two cores.
2. Cut the two points **(b)** to remove 1/4 turns of a core.
3. Apply silicone sealant (supplied) to **(c)** to secure remaining cores.

2. Burned-out COUP board (occurred on MF band)

Factory-modified Units:

Modification	FS-5000	FS-8000
① ②	2508-0095, 0096, 0105 and after	2522-0013 and after
③	2508-0070, 0071, 0072, 0074, 0077, 0078, 0080 and after	from first set
④	2508-0109, 0111, 0114 and after	2522-0017 and after

If the length of the antenna is proper (antenna impedance: 5 ohms, 200 pF or high) and no abnormality is found on the COUP board by voice test, omit this modification.

Modifications

	<u>Page</u>
① Clearance check of L8, L9, C19 to C26 (COUP PCB). -----	6
② Applying silicone sealant to the following parts: -----	6
[K25 to K27, T2 (COUP PCB) ----- Fig. 2]	
[K1 to K2, J1 to J2 (DUMMY LOAD PCB) ----- Fig. 3]	
③ Mounting arrester fixing metal to Antenna Coupler. -----	7
<i>NOTE: If there is a black label (●) at the bottom of the Antenna Coupler (near the earth clamp), the above modifications have been already done at factory.</i>	
④ Power reduction on 2.5 MHz or lower. -----	8
⑤ After making modifications, check for a sparking in the Antenna Coupler. -----	9




Fig. 2 COUP Board






Fig. 3 DUMMY LOAD Board

①

Coils L8 and L9




Capacitors C19 to C26





②

Relays K25 to K27 (Soldering Side)



Transformer T2



③ Mounting arrester fixing metal




Fig. 4 Antenna Coupler


④ Power reduction on 2.5 MHz or lower

Reduce power data to 225 for the FS-5000, 160 for the FS-8000. (About 320 Wpep at transceiver unit).

Channel	Resolution of Memory
User channel	Each channel
Free direct key-in ITU channel	500 kHz steps. That is, reduce the power <u>for two frequencies</u> . (One frequency between 1606.5 and 1999.9 kHz. The other frequency between 2000.0 and 2499.9 kHz.)

Procedure

1. Press the **STO** key followed by the **FULL** key. The screen should look something like this:



2. Press and hold down the **LOW** key until the "power data" is 225 for the FS-5000 or 160 for the FS-8000.
3. Press the **ENT** key to memorize the power data.

⑤ Spark check

After completing of items ① to ④, check for sparking.

Procedure

1. Set the TX frequency to the lowest one in use. (ex. 1632.5 kHz)
2. Press the TX TUNE key.
3. Observe the LEDs CR52 to CR57 (Fig. 2). Are they all OFF?
4. If they are not off, increase the TX frequency, then press the TX TUNE key to check the LEDs. Repeat this procedure until CR52 to CR57 are off.
5. Communicate with the handset (voice).
6. Check for sparking at the arrester.
7. If there is sparking (due to insufficient antenna capacity), do either remedy (1) or remedy (2).

Remedy (1): Reduce the power data until there is no sparking.

Remedy (2): Mount the provided antenna capacitor (for shunting, 50 pF or 100 pF) on the DUMMY LOAD board between the antenna terminal and ground. Further, modify this board to enable control of capacitor on and off. See the next page for these modifications.

Modification of DUMMY LOAD board
(installation of antenna capacitor)

This modification enables the antenna capacitor to be turned on in the specific range set by the system settings 9924 and 9925.

Procedure

1. Prepare optional DUMMY LOAD board (code no. 005-925-830).
2. Remove K1, C1 – C2 and R1 – R3.
3. Drill fixing hole for antenna capacitor. See Fig. 5.
4. Add a jumper wire as shown below to make shortcircuit between J1 and J2.




Fig. 5 DUMMY LOAD Board (Parts Side)

5. Referring to Fig. 5, fix antenna capacitor to board.
6. Solder a lug (supplied) to the earth pattern on the board.





Fig. 6 DUMMY LOAD Board (Soldering Side)

7. Apply silicone sealant (KE348T) to lead wires of J1, J2 and K2 to prevent leakage of high voltage.
8. Install the DUMMY LOAD board to the Antenna Coupler.
9. Be sure wiring does not contact other wirings and parts.



10. Change the system settings through keyboard.

- ① **STO** → 9923 → **ENT** → 2 → **ENT**
 - ② **STO** → 9924 → **ENT** → 1606.5 → **ENT**
(Lower limit)
 - ③ **STO** → 9925 → **ENT** → 2500.0 → **ENT**
(Upper Limit)
- } Frequency range in which antenna capacitor turns on.

11. Confirm that the LCD displays "S. CAP" when the frequency within the range set by 9924 and 9925 is used. Further, check that the **DUMMY** key turns the antenna capacitor on and off.

Note: The DUMMY LOAD board nullifies the dummy load function. If the dummy load is required, install an external dummy load.

3. Burned-out PA board over 22 MHz (Modification on PA board)

Continuous transmission for about 2 minutes at full power by single tone may damage the PA board.


Factory-modified Units:

FS-5000	FS-8000
2508-0071, 0073, 0074, 0078 and after	2522-0016 and after



Modifications:

- ① Replacement of transformer T4 (5T626 → 5T814)

Double-mounted transformer



- ② Removal of capacitors (16 pcs.) in hatched portions and soldering copper straps there.



Addenda No. 2 to Service Manual of FS-5000 Series SM-E5519



FS-5000/8000

Adjustment of Operating Temperature of Fan Motors

A potentiometer (R48) has been added on the PA board to enable adjustment of the operating temperature of fan motors, from the production in July 1991. In addition, the resistance value of R27 on the PA CHECK board has been changed to 1k ohms. When you replace previous versions of the PA board or the PA CHECK board, do the following adjustment.

1. Replacement of previous PA board with current PA board


Procedure

- (1) Change resistance value of R27 on the PA CHECK board to 1k ohms.
- (2) Turn on the unit and measure the temperature of the heat sink with a thermometer. Confirm that the measured temperature is nearly the same as the temperature indication on the LCD (25 °C to 35 °C). If it is not, adjust R48 on the PA board.

2. Replacement of previous PA CHECK board with current PA CHECK board

Procedure

- (1) Change resistance value of R27 on the PA CHECK board to 1k ohms.
- (2) Turn on the unit and measure the temperature of the heat sink with a thermometer. Confirm that the measured temperature is nearly the same as the temperature indication on the LCD (25 °C to 35 °C). If it is not, change resistance value of R27 so they agree, or add R48 on the PA board and adjust it.



FURUNO

Information

NO. : FQ5-91-010 ^{1/2}

Date : 1991 - 8

Issued by : FURUNO ELECTRIC CO., LTD.
QUALITY ASSURANCE DEPARTMENT

Addenda No. 3 to Service Manual of FS-5000 Series SM-E5519



FS-5000/8000 New EXC PCB and REG Assy.

The above units are equipped with a new EXC board and new REG assy. (incl. REG, REG CONT and REG SW boards). These new boards are not compatible with their previous versions.

1. EXC Board

Not compatible

	Type	Code No.
Previous	05P0349	005-594-240
	05P0349A	005-931-840
Current	05P0349-Z	005-943-070
	05P0349A-Z	005-943-100

Note : Suffix A represents FS-8000.

(1) Contents of Modification: Reference Oscillator section is deleted from previous EXC board. The REF OSC board (05P0414) is newly added.

(2) Factory Modification:

Model	Serial No.
FS-5000	2508-0114 to 0137, 0139 and after
FS-8000	2522-0017 and after

①

②

③

④

⑤

⑥

⑦

⑧

2. REG Assy.

	Name	Code No.
Previous	REG Assy.(24V)	005-942-450
	REG Assy.(32V)	005-931-830
Current	REG Assy.(24V)-Z...(Note 2)	005-943-040
	REG Assy.(32V)-Z...(Note 2)	005-943-050

Not compatible

Note 1. Current REG, REG CONT and REG SW boards are not compatible with previous ones, respectively.

2. REG assy. having version no. 3 on each of its boards represents current REG assy.

(1) Contents of Modification: Quantity (8pcs. →6pcs.) and fixing position of FETs on the REG SW board are changed.
In addition, the shape of heat sink has been changed.

(2) Factory Modification: Production in July 1991 and after.

FURUNO

Information

NO. : FQ5-91-011 1/2

Date: 1991 - 8

Issued by : FURUNO ELECTRIC CO., LTD.
QUALITY ASSURANCE DEPARTMENT

Addenda No. 4 to Service Manual of FS-5000 Series SM-E5519

FS-5000/8000

Program of ROM in Antenna Coupler Changed

The program of the ROM U3 on the COUP board in the Antenna Coupler has been changed, from version no. 2 to 3.

	Type	Code No.	S/No.
ROM	PROM05-501-32-103	592-743-000	FS-5000: 2508-0154 and after FS-8000: 2522-0017 and after




Photo No.1086

COUP Board

Reason for Modification

Automatic tuning sequence has been changed to allow use of the pi-network on 1.6 to 3.4 MHz, because these frequencies cannot be tuned on some long wire antenna installations.

Tuning Method

→
Automatic Tuning (3 times)

Band (MHz)	First		Second		Third		At retuning
	Network	SWR	Network	SWR	Network	SWR	SWR
Less than 2.56	Gamma	≤ 3.0	Gamma	≤ 3.0	Pi	≤ 3.0	≤ 2.0
2.56 to 3.36	Gamma	≤ 2.0	Gamma	≤ 2.0	Pi	≤ 2.0	≤ 2.0
3.36 to 5.12	Gamma	≤ 2.0	Pi	≤ 2.0			≤ 2.0
5.12 to 10.24	Pi	≤ 2.0	Gamma	≤ 2.0			≤ 2.0
More than 10.24	Pi	≤ 2.0	Pi	≤ 2.0			≤ 2.0

Newly added

Addenda No. 5 to Service Manual of FS-5000 Series SM-E5519

FS-1600/2500/5000/8000

Code No. Lists of Current PCBs & Assemblies

1. New REG Assy. added

	Name	Code No.	Remarks
Previous	REG Assy. (24V)	005-942-450	FOR 24VDC
	REG Assy. (32V)	005-931-830	FOR 32VDC
Current (*1)	REG Assy. (24V)-Z	005-943-040	FOR 24VDC
	REG Assy. (32V)-Z	005-943-050	FOR 32VDC

Quantity and fixing position of FETs are changed.

(*1) : Current REG assy. which consists of new REG/REG CONT/REG SW boards has a suffix Z or version no. 3 on its boards. If current REG assy. is used, use current PA PCB assy. shown in the list below, since current REG assy. can be combined with only new heat sink of PA PCB assy.

2. New PA PCB assy. (PA PCB plus heat sink) added

	Name	Code No.
Previous	PA PCB Assy.	005-941-810
Current (*2)	PA PCB Assy. (New)	005-943-060

Heat sinks of previous and current ones are different.

(*2) : New heat sink for current REG assy. is included.

3. PA/REG Assy. (New REG assy. plus New PA PCB assy. plus PA CHECK PCB) added

Power Supply	Name	Code No.
24VDC	PA/REG Assy.(24V)	005-943-020
32VDC	PA/REG Assy.(32V)	005-943-030

4. New EXC PCB added

EXC PCB	FS-5000		FS-8000	
	Type	Code No.	Type	Code No.
Previous	05P0349	005-594-240	05P0349A	005-931-840
Current	05P0349-Z	005-943-070	05P0349A-Z	005-943-100

} Not compatible

5. REF OSC PCB added ... 05P0414 (Code No. : 005-943-080)**6. INTERFACE PCB**

Power Supply	FS-5000/8000		FS-8000	
	Type	Code No.	Type	Code No.
24VDC	05P0354	005-927-250	05P0362	005-594-990
32VDC	05P0354A	005-943-090	05P0362A	005-943-120

7. TX FIL PCB

FS-5000		FS-8000	
Type	Code No.	Type	Code No.
05P0350	005-927-240	05P0350A	005-943-110


8. UNBALANCE DET PCB (only for FS-8000)... 05P0437 (Code No. : 005-943-130)**9. SWR PICK UP PCB (only for FS-8000)... 05P0413 (Code No. : 005-595-010)**

Note : Maintenance Parts List for Optional Supply

Name	Code No.
ANT BK RELAY PCB	005-594-710
CONTROLLER SW PCB	005-594-730
Dummy Load Assy.	005-927-610

ERROR MESSAGE LIST FOR SELF-TEST

If one of error messages listed below appears at self-test, check the corresponding parts.



Test No.	Error No.	Error Message	Check Point
9915/9916	1	CPU/Communication error	CPU board (in the transceiver unit) or Interconnection cable
9924/9925	1	CPU/Communication error	CPU board (in the control unit) or Interconnection cable
9923	2	No Tx AF signal on AF PCB	AF board
	3	No Rx AF sig. on AF PCB or TRx unit	
	4	No SQ AF signal on AF PCB	
	5	SQ not open on AF PCB	
	6	SQ not closed on AF PCB	
9913	7	Unlock freq. xxxx.xx kHz on RX PCB	RX board
9911	8	Unlock freq. xxxx.xx kHz on EXC PCB	EXC board
9914	9	No Rx signal through BPF on RX PCB	RX board
	10	No Rx signal through Pre-sel on RX PCB	
	11	No Rx signal on RX PCB	
	12	No S signal on RX PCB	
	13	Unable to control sensitivity on RX	
	14	Unable to mute Rx on RX PCB	

Continued

Test No.	Error No.	Error Message	Check Point
9912	15	No Mic signal from Control Unit on EXC	AF board, EXC board or Interconnection cable
	16	No Tx signal on EXC PCB	EXC board
	17	Unwanted Tx signal on EXC PCB	
	18	Insufficient source voltage	REG Unit (+ 18V line voltage)
	19	Insufficient PA Vc	REG Unit (+ 45V line voltage)
	20	Excessive PA idle current	PA board
	21	High temperature on PA	Temperature at PA board exceeds 80 °C.
	26	Unwanted Tx signal on PA or TX FIL PCB	PA board or TX FIL board
	29	No Tx signal on PA or TX FIL PCB	PA board, TX FIL board or Interconnection cable
9930	32	No acknowledge signal from Coupler	COUP board
	33	No Tx signal on PA	PA board
	35	No Tx signal on TX FIL PCB	TX FIL board

FURUNO

Information

NO. : FQ5-91-014 1/2

Date : 1991 - 9

Issued by : FURUNO ELECTRIC CO., LTD.
QUALITY ASSURANCE DEPARTMENT

Addenda No. 7 to Service Manual of FS-5000 SM-E5519

FS-5000/8000 ROM PROGRAM CHANGE (Ver. 7)

ROMs on the Control and Transceiver Units have been changed from "6" to "7" from August 1991.

	Type	Code No.
NEW ROM	PROM 05-501-31-107	005-927-440

Contents of Modification

1. Receiver Functions

- (1) The beep associated with the following function keys has been disabled as it has proved to be a hindrance.

[TUNE], [PRESELECTOR], [SENSITIVITY], [VOLUME]

- (2) Automatic selection of duplex filter and preselector in duplex mode, depending on the RX frequency.

RX freq.	Preselector	Duplex filter
4MHz or less	ON	OFF
4 to 4.5 MHz	OFF	ON

Note that preselector status is restored to previous setting when simplex mode is selected on 4 to 4.5MHz.

- (3) Speaker is automatically switched on when changing the communication mode from DUPLEX to SIMPLEX.

2. Transmitter Functions

- (1) A beep(s) has been added after completion of TX TUNE operation.

OK result: "beep"
Error result: "beep-beep-beep"

- (2) The time interval for detection of PA temperature has been lengthened to protect rapid power reduction due to high temperature at PA.

Interval: Previous 2 seconds → Current 5 minutes

- (3) Automatic turn-off for dummy load: If TX frequency is changed with the dummy load turned ON, the dummy load will automatically be turned OFF. (For FS-8000, the DUMMY operation is inactive on the HF band.)

3. System Settings

- (1) Additional system setting allowing free selection of TX frequency within marine bands; by entering the following commands:

[STO] 9901 [ENT] 3 [ENT]

Any frequency in the following bands may be transmitted.

1606.5- 4438, 6200 - 6525, 8100 - 8815, 12230 -13200, 16360 -17410,	18780-18900, 19680-19800, 22000-22855, 25070-25210, 26100-26175	(unit: kHz)
---------------------------------------------------------------------------------	-----------------------------------------------------------------------------	-------------

- (2) System setting #9902 has been deleted.
(New ITU frequencies are now in use.)
- (3) Change of setting range of #9913 (System delay time).
(10 to 99ms → 5 to 99ms)
Note that system delay time is now 10ms (minimum) even if you set #9913 for "5ms".

FURUNO

Information

NO. : FQ5-91-015

Date : 1991 - 9

Issued by : FURUNO ELECTRIC CO., LTD.
QUALITY ASSURANCE DEPARTMENT

Addenda No. 8 to Service Manual of FS-5000 SM-E5519


FS-5000/8000

Remedy for TX Frequency Deviation

Symptom: You can not transmit due to synthesizer unlock, or another station can not receive your signal clearly.

Cause: 3rd local oscillation unlocks because of excessive input level of U8 (mixer) in the SYN section on the EXC board.

Remedy: Change R70 from 10K ohms to 470 ohms (Code No.: 000-117-177), or add 470 ohms in parallel with R70. Do this remedy at next ship visit.



Factory Modification: From the production in August 1991.

①

②

③

④

⑤

⑥

⑦

⑧

MAINTENANCE PARTS LIST
FOR FS-5000/8000

NO.M61900

DATE 7/10/91

PAGE 1

*1:DEPOT MAINTENANCE PARTS FOR 10 SETS IN 2 YEARS
*2:SHIPBORNE RUNNING PARTS FOR 1 SET IN 2 YEARS

CODE NO.	NAME OF PARTS	TYPE	SPECIFICATIONS	QUANTITY		REMARKS
				*1	*2	
000-119-440	TRANSISTOR	MRF-448MP	05S0546-1	6	2	PA PCB (2 PAIRS)
000-121-823	MOS FET	IRFP150		6	2	REG SW PCB
000-104-429	DIODE	05AZ18Z	ZENER	6	2	REG SW PCB
000-106-066	RELAY	JR1-DC12V	AJR3221	1	1	TX FIL PCB (50 OHMS BK)
000-106-068	RELAY	JC1AF-DC12V	AR321173	3	1	COUP PCB
000-106-069	RELAY	FRD-12023		3	1	COUP PCB
000-106-216	RELAY	JC2AF-DC12V	AR322173	3	1	COUP PCB
000-116-371	RELAY	HD1-M-DC12V	AG4013	1	1	RX PCB
000-119-485	RELAY	JR1A-DC12V	AJR3211	3	1	COUP PCB
000-445-356	RELAY	JH2A-DC24V	AR5222	1	1	INTERFACE PCB
000-113-376	CRYSTAL	05S0402-0	49.5MHZ 05S0402-0	1	1	EXC PCB
000-119-322	FAN MOTOR	MD1225A-24		1		FOR PA COOLING
000-121-337	MOTOR	109E0824H402		1		
000-580-091	LOUDSPEAKER	EAS-65P16S	8, 2W	1		
000-112-623	HANDSET WITH CURL CORD	HS6000FZ5		1	1	
000-835-126	NI-CD BATTERY	N-50SB3		2		
005-594-140	PRINTED CIRCUIT BOARD	05P0367	PA CHECK	3	1	
005-594-200	PRINTED CIRCUIT BOARD	05P0347	CPU	3	1	TRANSCEIVER UNIT
005-594-220	PRINTED CIRCUIT BOARD	05P0348	RX	3	1	
005-594-240	PRINTED CIRCUIT BOARD	05P0349	EXC	3	1	OLD ONE. ONLY FOR FS-5000
005-594-290	PRINTED CIRCUIT BOARD	05P0358	COUPLER	3	1	
005-594-520	PRINTED CIRCUIT BOARD	05P0357	KEY	3	1	
005-594-540	PRINTED CIRCUIT BOARD	05P0355	CPU	3	1	CONTROL UNIT
005-594-560	PRINTED CIRCUIT BOARD	05P0356	AF	3	1	
005-594-710	PRINTED CIRCUIT BOARD	05P0359	ANT BK RELAY	1		OPTION
005-594-730	PRINTED CIRCUIT BOARD	05P0368	CONTROLLER SW	1		OPTION
005-594-990	PRINTED CIRCUIT BOARD	05P0362	I/F 24V	3	1	ONLY FOR FS-8000/24VDC
005-595-010	PRINTED CIRCUIT BOARD	05P0413	SWR PICKUP	3	1	ONLY FOR FS-8000
005-927-240	PRINTED CIRCUIT BOARD	05P0350	TX FIL	3	1	ONLY FOR FS-5000
005-927-250	PRINTED CIRCUIT BOARD	05P0354	I/F 24V	3	1	FOR 24VDC SET
005-927-460	PRINTED CIRCUIT BOARD	LM24008M	LCD	3	1	
005-927-610	DUMMY LOAD PCB ASSEMBLY	05P0360		1		OPTION. W/MOUNTING PLATE
005-931-830	REG ASSEMBLY (32V)	FS-5000/8000T	REG/R CONT.P.	3	1	OLD ONE. FOR 32VDC SET
005-931-840	PRINTED CIRCUIT BOARD	05P0349A	EXC	3	1	OLD ONE. ONLY FOR FS-8000
005-941-810	PA PCB ASSEMBLY	05P0363	W/HEAT SINK	3	1	OLD ONE
005-942-450	REG ASSEMBLY (24V)	FS-5000/8000T	REG/R CONT.P.	3	1	OLD ONE. FOR 24VDC SET
005-943-020	PA/REG ASSEMBLY (24V)	05P0363	W/REG.SHIELD	1		FOR 24VDC SET
005-943-030	PA/REG ASSEMBLY (32V)	05P0363A	W/REG COVER	1		FOR 32VDC SET
005-943-040	REG ASSEMBLY (24V)-Z	05P0352Z/353Z/398Z		3	1	NEW ONE. FOR 24VDC SET

The following shows current maintenance parts list.

FS-5000/8000
Maintenance Parts List Changed

Addenda No.9 to Service Manual of FS-5000 SM-E5519

MAINTENANCE PARTS LIST
FOR FS-5000/8000

NO.M61900

DATE 7/10/91

PAGE 2

CODE NO.	NAME OF PARTS	TYPE	SPECIFICATIONS	QUANTITY		REMARKS
				*1	*2	
005-943-050	REG ASSEMBLY (32V)-Z	05P0352Z/353AZ/398Z	FS-5000T/8000T	3	1	NEW ONE. FOR 32VDC SET
005-943-060	PA PCB ASSEMBLY-Z	05P0363 W/HEAT SINK	FS-5000T/8000T	3	1	NEW ONE
005-943-070	PRINTED CIRCUIT BOARD	05P0349-Z EXC	FS-5000T	3	1	NEW ONE. ONLY FOR FS-5000
005-943-080	PRINTED CIRCUIT BOARD	05P0414 REF OSC	FS-5000T/8000T	3	1	
005-943-090	PRINTED CIRCUIT BOARD	05P0354A I/F	FS-5000T/8000T	3	1	FOR 32VDC SET
005-943-100	PRINTED CIRCUIT BOARD	05P0349A-Z EXC	FS-8000T	3	1	NEW ONE. ONLY FOR FS-8000
005-943-110	PRINTED CIRCUIT BOARD	05P0350A TX FIL	FS-8000T	3	1	ONLY FOR FS-8000
005-943-120	PRINTED CIRCUIT BOARD	05P0362A I/F 32V	FS-8000T	3	1	ONLY FOR FS-8000/32VDC
005-943-130	PRINTED CIRCUIT BOARD	05P0437 UNBAL DET	FS-8000T	3	1	ONLY FOR FS-8000
000-119-467	FLEXIBLE CABLE	SMCD-1.25-20-400-NBD		1	1	CONTROL UNIT

2/2

FURUNO

Information

NO. : FQ5-91-018

1/5

Date: 1991 - 10

Issued by : FURUNO ELECTRIC CO., LTD.
QUALITY ASSURANCE DEPARTMENT

Addenda No. 10 to Service Manual of FS-5000 SM-E5519

FS-5000/8000 New Version ROM (No. 8)

The version no. of the ROMs on the control and transceiver units have been changed from 7 to 8 in September 1991.

CONTENTS OF MODIFICATION

1. ITU Frequency Table for USA has been added. (SSB only)

.....Selectable with new system setting 9961.

Calling Procedure

① [STO] "9961" [ENT]

The following menu appears:

ITU Freq. Table [0-INT, 1-USA]

② "1" [ENT]

Details of ITU Frequency Table for USA ...Refer to attached sheet.

(1) The following channels were omitted from standard ITU Frequency Table as they are not specified by the FCC:

429-452 609-611 833-835 838-870 1238-1246 1650-1663 1816-1822
2248-2260 2511-2517

(2) Simplex channels are re-arranged to start from No. 61 as follows:

461:4146 661:6224 861:8294 1261:12353 1661:16528 1861:18840
462:4149 662:6227 862:8297 1262:12356 1662:16531 1862:18843
463:4417 663:6230 1263:12359 1663:16534
664:6516

2261:22159 2561:25115
2262:22162 2562:25118
2263:22165
2264:22168
2265:22171

(3) Mississippi River channels are re-arranged to start from No. 71 as follows:

471:4065	671:6209	871:8201	1271:12362	1671:16543
472:4089	672:6212	872:8213	1272:12365	1672:16546
473:4116	673:6510	873:8725		
474:4408	674:6513	874:8737		

(4) Alaska Radio channels are re-arranged to start from No. 81 as follows:

481:4366
 482:4369
 483:4396
 484:4402
 485:4420
 486:4423

(5) Transmission frequencies of three duplex channels have been changed as follows:

	<u>Previous T-R</u>	<u>Current T-R</u>
428:	4351-4351	4060-4351
836:	8713-8713	8113-8713
837:	8716-8716	8128-8716

(6) Distress channel numbers are re-arranged so that they all end with a zero.

300:3023
 400:4125
 500:5680
 600:6215
 800:8291
 1200:12290
 1600:16420

2. In standard ITU Frequency Table, distress channel numbers are re-arranged as follows:

300:3023
 400:4125
 500:5680
 600:6215
 800:8291
 1200:12290
 1600:16420

3. 5680 kHz has been added to the "Marine Band" ("9901") Table.

4. GMDSS Frequency changes ... (Calling Procedure: [DSC] "Channel No." [ENT])

<u>Ch. No.</u>	<u>Frequency</u>	<u>Remarks</u>
7	500	moved from CH10
8	3023	added (SSB)
9	5680	added (SSB)
51	T2189.5-R2177	corrected (Telex)
52	T2177-R2177	corrected (Telex)

5. High temperature threshold of thermal protection circuit on PA section has been changed from 80°C to 90°C.

6. Software bug amended: Tuning was sometimes done twice.

FACTORY MODIFICATION

Model	Serial Number
FS-5000	2508-0223 to 0227, 0232 and after
FS-8000	2522-0019 and after

ROM CODE NUMBER

Type	Code No.
PROM 05-501-31-108	005-927-440



USA SSB FREQUENCY TABLE FOR FURUNO SSB RADIOTELEPHONES

SSBUSA 4/5

1 4 MHz BAND			2 6 MHz BAND			3 8 MHz BAND			4 12 MHz BAND			5 16 MHz BAND			6 18/19 MHz BAND			7 22 MHz BAND			8 25/26 MHz BAND			Remarks			
No.	TX	RX	No.	TX	RX	No.	TX	RX	No.	TX	RX	No.	TX	RX	No.	TX	RX	No.	TX	RX	No.	TX	RX				
300	3023	3023	600	6215	6215	800	8291	8291	1200	12290	12290	1600	16420	16420													Distress Channels
401	4065	4357	601	6200	6501	801	8195	8719	1201	12230	13077	1601	16360	17242	1801	18780	19755	2201	22000	22696	2501	25070	26145				ITU SSB Duplex Channels
402	4068	4360	602	6203	6504	802	8198	8722	1202	12233	13080	1602	16363	17245	1802	18783	19758	2202	22003	22699	2502	25073	26148				
403	4071	4363	603	6206	6507	803	8201	8725	1203	12236	13083	1603	16366	17248	1803	18786	19761	2203	22006	22702	2503	25076	26151				
404	4074	4366	604	6209	6510	804	8204	8728	1204	12239	13086	1604	16369	17251	1804	18789	19764	2204	22009	22705	2504	25079	26154				
405	4077	4369	605	6212	6513	805	8207	8731	1205	12242	13089	1605	16372	17254	1805	18792	19767	2205	22012	22708	2505	25082	26157				
406	4080	4372	606	6215	6516	806	8210	8734	1206	12245	13092	1606	16375	17257	1806	18795	19770	2206	22015	22711	2506	25085	26160				
407	4083	4375	607	6218	6519	807	8213	8737	1207	12248	13095	1607	16378	17260	1807	18798	19773	2207	22018	22714	2507	25088	26163				
408	4086	4378	608	6221	6522	808	8216	8740	1208	12251	13098	1608	16381	17263	1808	18801	19776	2208	22021	22717	2508	25091	26166				
409	4089	4381				809	8219	8743	1209	12254	13101	1609	16384	17266	1809	18804	19779	2209	22024	22720	2509	25094	26169				
410	4092	4384				810	8222	8746	1210	12257	13104	1610	16387	17269	1810	18807	19782	2210	22027	22723	2510	25097	26172				
411	4095	4387				811	8225	8749	1211	12260	13107	1611	16390	17272	1811	18810	19785	2211	22030	22726							
412	4098	4390				812	8228	8752	1212	12263	13110	1612	16393	17275	1812	18813	19788	2212	22033	22729							
413	4101	4393				813	8231	8755	1213	12266	13113	1613	16396	17278	1813	18816	19791	2213	22036	22732							
414	4104	4396				814	8234	8758	1214	12269	13116	1614	16399	17281	1814	18819	19794	2214	22039	22735							
415	4107	4399				815	8237	8761	1215	12272	13119	1615	16402	17284	1815	18822	19797	2215	22042	22738							
416	4110	4402				816	8240	8764	1216	12275	13122	1616	16405	17287				2216	22045	22741							
417	4113	4405				817	8243	8767	1217	12278	13125	1617	16408	17290				2217	22048	22744							
418	4116	4408				818	8246	8770	1218	12281	13128	1618	16411	17293				2218	22051	22747							
419	4119	4411				819	8249	8773	1219	12284	13131	1619	16414	17296				2219	22054	22750							
420	4122	4414				820	8252	8776	1220	12287	13134	1620	16417	17299				2220	22057	22753							
421	4125	4417				821	8255	8779	1221	12290	13137	1621	16420	17302				2221	22060	22756							
422	4128	4420				822	8258	8782	1222	12293	13140	1622	16423	17305				2222	22063	22759							
423	4131	4423				823	8261	8785	1223	12296	13143	1623	16426	17308				2223	22066	22762							
424	4134	4426				824	8264	8788	1224	12299	13146	1624	16429	17311				2224	22069	22765							
425	4137	4429				825	8267	8791	1225	12302	13149	1625	16432	17314				2225	22072	22768							
426	4140	4432				826	8270	8794	1226	12305	13152	1626	16435	17317				2226	22075	22771							
427	4143	4435				827	8273	8797	1227	12308	13155	1627	16438	17320				2227	22078	22774							
428	4060	4351				828	8276	8800	1228	12311	13158	1628	16441	17323				2228	22081	22777							
						829	8279	8803	1229	12314	13161	1629	16444	17326				2229	22084	22780							
						830	8282	8806	1230	12317	13164	1630	16447	17329				2230	22087	22783							
						831	8285	8809	1231	12320	13167	1631	16450	17332				2231	22090	22786							
						832	8288	8812	1232	12323	13170	1632	16453	17335				2232	22093	22789							
									1233	12326	13173	1633	16456	17338				2233	22096	22792							
									1234	12329	13176	1634	16459	17341				2234	22099	22795							
									1235	12332	13179	1635	16462	17344				2235	22102	22798							
						836	8113	8713	1236	12335	13182	1636	16465	17347				2236	22105	22801							
						837	8128	8716	1237	12338	13185	1637	16468	17350				2237	22108	22804							
												1638	16471	17353				2238	22111	22807							
												1639	16474	17356				2239	22114	22810							
												1640	16477	17359				2240	22117	22813							
												1641	16480	17362				2241	22120	22816							
												1642	16483	17365				2242	22123	22819							
												1643	16486	17368				2243	22126	22822							
												1644	16489	17371				2244	22129	22825							
												1645	16492	17374				2245	22132	22828							
												1646	16495	17377				2246	22135	22831							
												1647	16498	17380				2247	22138	22834							
												1648	16501	17383													
												1649	16504	17386													
461	4146	4146	661	6224	6224	861	8294	8294	1261	12353	12353	1661	16528	16528	1861	18840	18840	2261	22159	22159	2561	25115	25115				Simplex Channels
462	4149	4149	662	6227	6227	862	8297	8297	1262	12356	12356	1662	16531	16531	1862	18843	18843	2262	22162	22162	2562	25118	25118				
463	4417	4417	663	6230	6230				1263	12359	12359	1663	16534	16534				2263	22165	22165							
			664	6516	6516													2264	22168	22168							
																		2265	22171	22171							
471	4065	4065	671	6209	6209	871	8201	8201	1271	12362	12362	1671	16543	16543													Mississippi River Channels
472	4089	4089	672	6212	6212	872	8213	8213	1272	12365	12365	1672	16546	16546													
473	4116	4116	673	6510	6510	873	8725	8725																			
474	4408	4408	674	6513	6513																						

4 MHz BAND			6 MHz BAND			8 MHz BAND			12 MHz BAND			16 MHz BAND			18/19 MHz BAND			22 MHz BAND			25/26 MHz BAND					
No.	TX	RX	No.	TX	RX	No.	TX	RX	No.	TX	RX	No.	TX	RX	No.	TX	RX	No.	TX	RX	No.	TX	RX			
300	3023	3023	600	6215	6215	800	8291	8291	1200	12290	12290	1600	16420	16420												
400	4125	4125																								
500	5680	5680																								
401	4065	4357	601	6200	6501	801	8195	8719	1201	12230	13077	1601	16360	17242	1801	18780	19755	2201	22000	22696	2501	25070	26145			
402	4068	4360	602	6203	6504	802	8198	8722	1202	12233	13080	1602	16363	17245	1802	18783	19758	2202	22003	22699	2502	25073	26148			
403	4071	4363	603	6206	6507	803	8201	8725	1203	12236	13083	1603	16366	17248	1803	18786	19761	2203	22006	22702	2503	25076	26151			
404	4074	4366	604	6209	6510	804	8204	8728	1204	12239	13086	1604	16369	17251	1804	18789	19764	2204	22009	22705	2504	25079	26154			
405	4077	4369	605	6212	6513	805	8207	8731	1205	12242	13089	1605	16372	17254	1805	18792	19767	2205	22012	22708	2505	25082	26157			
406	4080	4372	606	6215	6516	806	8210	8734	1206	12245	13092	1606	16375	17257	1806	18795	19770	2206	22015	22711	2506	25085	26160			
407	4083	4375	607	6218	6519	807	8213	8737	1207	12248	13095	1607	16378	17260	1807	18798	19773	2207	22018	22714	2507	25088	26163			
408	4086	4378	608	6221	6522	808	8216	8740	1208	12251	13098	1608	16381	17263	1808	18801	19776	2208	22021	22717	2508	25091	26166			
409	4089	4381	609	6224	6525	809	8219	8743	1209	12254	13101	1609	16384	17266	1809	18804	19779	2209	22024	22720	2509	25094	26169			
410	4092	4384	610	6227	6528	810	8222	8746	1210	12257	13104	1610	16387	17269	1810	18807	19782	2210	22027	22723	2510	25097	26172			
411	4095	4387	611	6230	6531	811	8225	8749	1211	12260	13107	1611	16390	17272	1811	18810	19785	2211	22030	22726	2511	25100	26175			
412	4098	4390				812	8228	8752	1212	12263	13110	1612	16393	17275	1812	18813	19788	2212	22033	22729	2512	25103	26178			
413	4101	4393				813	8231	8755	1213	12266	13113	1613	16396	17278	1813	18816	19791	2213	22036	22732	2513	25106	26181			
414	4104	4396				814	8234	8758	1214	12269	13116	1614	16399	17281	1814	18819	19794	2214	22039	22735	2514	25109	26184			
415	4107	4399				815	8237	8761	1215	12272	13119	1615	16402	17284	1815	18822	19797	2215	22042	22738	2515	25112	26187			
416	4110	4402				816	8240	8764	1216	12275	13122	1616	16405	17287	1816	18825	19800	2216	22045	22741	2516	25115	26190			
417	4113	4405				817	8243	8767	1217	12278	13125	1617	16408	17290	1817	18828	19803	2217	22048	22744	2517	25118	26193			
418	4116	4408				818	8246	8770	1218	12281	13128	1618	16411	17293	1818	18831	19806	2218	22051	22747						
419	4119	4411				819	8249	8773	1219	12284	13131	1619	16414	17296	1819	18834	19809	2219	22054	22750						
420	4122	4414				820	8252	8776	1220	12287	13134	1620	16417	17299	1820	18837	19812	2220	22057	22753						
421	4125	4417				821	8255	8779	1221	12290	13137	1621	16420	17302	1821	18840	19815	2221	22060	22756						
422	4128	4420				822	8258	8782	1222	12293	13140	1622	16423	17305	1822	18843	19818	2222	22063	22759						
423	4131	4423				823	8261	8785	1223	12296	13143	1623	16426	17308				2223	22066	22762						
424	4134	4426				824	8264	8788	1224	12299	13146	1624	16429	17311				2224	22069	22765						
425	4137	4429				825	8267	8791	1225	12302	13149	1625	16432	17314				2225	22072	22768						
426	4140	4432				826	8270	8794	1226	12305	13152	1626	16435	17317				2226	22075	22771						
427	4143	4435				827	8273	8797	1227	12308	13155	1627	16438	17320				2227	22078	22774						
428	4351	4351				828	8276	8800	1228	12311	13158	1628	16441	17323				2228	22081	22777						
429	4354	4354				829	8279	8803	1229	12314	13161	1629	16444	17326				2229	22084	22780						
430	4146	4146				830	8282	8806	1230	12317	13164	1630	16447	17329				2230	22087	22783						
431	4149	4149				831	8285	8809	1231	12320	13167	1631	16450	17332				2231	22090	22786						
432	4000	4000				832	8288	8812	1232	12323	13170	1632	16453	17335				2232	22093	22789						
433	4003	4003				833	8291	8815	1233	12326	13173	1633	16456	17338				2233	22096	22792						
434	4006	4006				834	8294	8818	1234	12329	13176	1634	16459	17341				2234	22099	22795						
435	4009	4009				835	8297	8821	1235	12332	13179	1635	16462	17344				2235	22102	22798						
436	4012	4012				836	8299	8824	1236	12335	13182	1636	16465	17347				2236	22105	22801						
437	4015	4015				837	8302	8827	1237	12338	13185	1637	16468	17350				2237	22108	22804						
438	4018	4018				838	8305	8830	1238	12341	13188	1638	16471	17353				2238	22111	22807						
439	4021	4021				839	8308	8833	1239	12344	13191	1639	16474	17356				2239	22114	22810						
440	4024	4024				840	8311	8836	1240	12347	13194	1640	16477	17359				2240	22117	22813						
441	4027	4027				841	8314	8839	1241	12350	13197	1641	16480	17362				2241	22120	22816						
442	4030	4030				842	8317	8842	1242	12353	13200	1642	16483	17365				2242	22123	22819						
443	4033	4033				843	8320	8845	1243	12356	13203	1643	16486	17368				2243	22126	22822						
444	4036	4036				844	8323	8848	1244	12359	13206	1644	16489	17371				2244	22129	22825						
445	4039	4039				845	8326	8851	1245	12362	13209	1645	16492	17374				2245	22132	22828						
446	4042	4042				846	8329	8854	1246	12365	13212	1646	16495	17377				2246	22135	22831						
447	4045	4045				847	8332	8857				1647	16498	17380				2247	22138	22834						
448	4048	4048				848	8335	8860				1648	16501	17383				2248	22141	22837						
449	4051	4051				849	8338	8863				1649	16504	17386				2249	22144	22840						
450	4054	4054				850	8341	8866				1650	16507	17389				2250	22147	22843						
451	4057	4057				851	8344	8869				1651	16510	17392				2251	22150	22846						
452	4060	4060				852	8347	8872				1652	16513	17395				2252	22153	22849						
						853	8350	8875				1653	16516	17398				2253	22156							

Addenda No. 11 to Service Manual of FS-5000 SM-E5519


FS-5000/8000

Photo Coupler for Telegraph Key Input Damaged

- Symptom : Telegraph key input does not function.
- Cause : When the POWER switch is turned off, the voltage charged by C55 on the AF board in the Control Unit is fed to photo coupler U12 (diode) and may cause U12 to be damaged.

C55 Charging voltage : 18V
 U12 Reverse voltage (max.) : $V_R = 6V$

- Remedy : Replace U12 with a new one and add diode 1SS133 (code no. : 000-103-097) in parallel with U12 as shown in the figure below.



AF board (Soldering side)

Note: If more than 40V is fed to the key input line, CR4 and U12 may be damaged. Confirm that key input line is not connected to other equipment.

Factory Modication : Delivery from October 1991 and after.

FURUNO

Information

NO. : FQ5-92-012

Date: 1992 - 4

Issued by : FURUNO ELECTRIC CO., LTD.
QUALITY ASSURANCE DEPARTMENT

Addenda No. 12 to Service Manual of FS-5000 SM-E5519

FS-5000/8000 Modification of TX FIL PCB

Symptom : "Excessive IC on PA" is observed on 12MHz.
(Power is automatically reduced, or the breaker of the PR-850 is shut down.)

Cause : Impedance on 12MHz in the TX FIL board viewed from the PA board is less than 50 ohms.

Factory

Modification : Capacitance (for 12MHz or higher) in the TX FIL board has been changed as follows.

- C41 : Deleted (100pF)
- C43 : 27pF ⇒ 56pF (27pF added in parallel with C43)
- C47 : 82pF ⇒ 100pF (22pF added in parallel with C47)
- C49 : 68pF ⇒ 47pF

Model	Serial No.
FS-5000	2508-0367 and after
FS-8000	2522-0046 and after

Field

Modification : Power data on each band should be reduced until IC on PA board becomes less than 21A.

Power data adjustment procedure:

1. Set TX frequency to desired band. (ex. 12MHz)
2. Press [STO] key followed by [FULL] key.
3. Press and hold [LOW] key to decrease the power data.
4. Transmit single tone. (Press [TEST TONE] key, then press PTT switch.)... *Note 1*
5. Check IC indication on the LCD. If IC display does not exceed 21A, release the PTT switch then press [ENT] key to memorize the power data.
6. Repeat steps 1 to 5 for all bands.

Note 1: To use test tone, change system setting as follows.

[STO] 9926 [ENT] 0 [ENT]

FURUNO

Information

NO. : FQ5-92-007

Date : 1992 - 4

Issued by : FURUNO ELECTRIC CO., LTD.
QUALITY ASSURANCE DEPARTMENT

Addenda No. 13 to Service Manual of FS-5000 SM-E5519



FS-5000/8000 Modification for Power Failure

Symptom : Power can not be supplied when pressing the [POWER] key. ①

Cause : Transmission signal from the FS-5000 itself is induced to the AF and INTERFACE boards due to improper ground, etc. (self-induction) ②

Remedy : Change resistance values (chip resistors) in the AF and INTERFACE boards as follows. ③

AF board

R70/R71 : 100 ohms \Rightarrow 330 ohms. (Carbon, 1/6W) ④

INTERFACE board

R18/R19 : 100 ohms \Rightarrow 330 ohms. (Carbon, 1/6W)



⑤

⑥

⑦

⑧

FURUNO

Information

NO. : FQ5-92-006

Date : 1992 - 4

Issued by : FURUNO ELECTRIC CO., LTD.
QUALITY ASSURANCE DEPARTMENT

Addenda No. 14 to Service Manual of FS-5000 SM-E5519

FS-5000/8000 Change of MIC Gain Adjustment

The MIC gain adjustment has been changed as below from Jan. 1992 to facilitate the factory adjustment.

Please amend pages 2-4 and 2-14 of the FS-5000 Service Manual.

Pages 2-4 and 2-14

Previous

Adjust **R6** on the EXC board for the output power of 100W for FS-5000, 200W for FS-8000.

(TX freq: 16MHz, SSB,

MIC input level: 1500Hz, **-54dBm**,

PTT: ON, Power data: 255)



New

Find the frequency (1.6 to 25MHz) which the output power of the transceiver unit is the lowest, when the MIC input level is **-53dBm** of single tone. Then adjust **R8** on the EXC board for the output power of 100W for FS-5000, 200W (100W on MF band) for FS-8000.

Note: Power data

FS-5000 ... 255 (HF)
FS-8000 ... 255(HF)
180 (MF)

This adjustment is done at the factory. When you change the EXC or PA board locally, confirm the MIC gain adjustment if possible.


Addenda No. 15 to Service Manual of FS-5000 SM-E5519

Errata and Addition of MIF Description for FS-5000 Service Manual


1. Amendment

Please amend the following pages of the Service Manual.

(1) Page AP2-8



(2) Page AP2-9




2. Addition of MIF description

We use MIF (Furuno Radio Interface), a handshaking type signal exchange system using TXD and RXD, for remote operation. Refer to the next page.

MIF FORMAT

MIF is a handshaking type signal exchange system developed by FURUNO for remote control of newly developed FURUNO radio equipment; for example, DP-5, FS-5000, FS-8000, DSC-5 and others.

Example for interconnection



* All data are communicated in MIF format.

CAUTION


Furuno will assume no responsibility for the inconvenience/disturbance to communications or unlawful emission due to inadequate command from personal computer.

SPECIFICATION OF MIF

1. Communication System: Serial asynchronous (half-duplex)

2. Baud Rate: 4800 BPS standard
(1200/2400/9600 BPS selectable)

3. Character Format



Start	: 1 bit	} -----> 11 bit
Data	: 7 bit (B1 to B7)	
Parity	: 1 bit (Even)	
Stop	: 2 bit	

4. Signal Level (RS-232C compatible, except FM-7000)

Name	Space	Mark
Logic	0 (ON)	1 (OFF)
Output	+ 5 to + 15 V	- 15 to - 5 V
Input	≥ 3 V	≤ - 3 V

* FM-7000 ----- Current Loop (± 20 mA)


7. Response Output

1 * CR (LF) ----- When the command is correctly executed.

2 ? CR (LF) ----- When incorrect command is input, or error takes place during execution of the command.

Time out: 1 sec.

Retry: 3 times (60 sec only for tune command ("TU"))



Control	Command	Parameter
SQUELCH	SQ	10 : 2 digits To adjust squelch threshold, enter hexadecimal code; FF provides tightest squelch. S : 1 digit S: Squelch ON R: Squelch OFF
NOISE BLANKER	NB	S : 1 digit S: Noise Blanker ON R: Noise Blanker OFF 10 : 2 digits To adjust sensitivity of noise blanker, enter hexadecimal code (00-FF); FF is highest threshold.
SPEAKER CONTROL	SP	S : 1 digit S: Speaker ON R: Speaker OFF
MUTE	MU	S : 1 digit S: Mute ON R: Mute OFF
BK	BK	S : 1 digit S: BK ON R: BK OFF
TX	TX	S : 1 digit S: TX ON R: TX OFF
EXCITER	EX	S : 1 digit S: Exciter ON R: Exciter OFF
TUNING	TU	No fixed parameter (Time out: 15 sec)
SPEAKER VOLUME	AF	U : 1 digit U: Increase Volume D: Decrease Volume 10 : 2 digits Enter hexadecimal code (00-FF); FF for maximum volume
SENSITIVITY	RF	U : 1 digit, same as "speaker volume" 10 : 2 digits, same as speaker volume.

continued

Control	Command	Parameter
DIMMER	DI	<p>S : 1 digit</p> <p>S: Dimmer ON U: Brighten R: Dimmer OFF D: Dim</p> <p>0 F : 2 digits</p> <p>Enter hexadecimal code (00-FF); FF for maximum brightness.</p>
RF POWER	PO	<p>0 to 3 : 1 digit</p> <p>3: Full Power 1: Low Power 2: Mid Power 0: Zero Power</p> <p>1 0 : 2 digits</p> <p>Enter hexadecimal code (00-FF); FF for maximum RF power.</p>
RAISE FRE- QUENCY, CHANNEL	UP	<p>0 to 7 : 1 digit</p> <p>0: Raise Channel by one 4: Raise Freq. by 10 kHz 1: Raise Freq. by 10 Hz 5: Raise Freq. by 100 kHz 2: Raise Freq. by 100 Hz 6: Raise Freq. by 1 MHz 3: Raise Freq. by 1 kHz 7: Raise Freq. by 10 MHz</p>
LOWER FRE- QUENCY, CHANNEL	DN	<p>1 : 1 digit</p> <p>Same as above</p>
CHANNEL NUMBER	CH	<p>0001 : 4 digits --- retain current channel number.</p> <p>U001 : 4 digits --- U (W, N or P) + 3 digit ch. No. [U: USA, W: Weather, N: International, P: Private]</p> <p>PF01 : 4 digits --- PX + 2 digit ch. No. [X: F, P, L or M]</p> <p>G0101 : 5 digits --- G + 2 digit group No. + 2 digit ch. No. (for group ch.)</p> <p>I01001 : 6 digits --- I + 2 digit band No. + 3 digit ch. No. (for ITU ch.)</p>
WRITE TO MEMORY	ST	Same as for channel number
RECALL FROM MEMORY	RC	Same as for channel number
FSK SHIFT WIDTH	FS	<p>0 to 2 : 1 digit</p> <p>0: 850 Hz 1: 425 Hz 2: 170 Hz</p> <p>850 : 3 digits (desired width in Hz)</p>
DUPLEX, SIMPLEX	DU	<p>S : 1 digit</p> <p>S: Duplex ON 0: Full Duplex R: Duplex OFF 1: Semi Duplex 2: Simplex</p>
FREQUENCY SCANNING	SC	<p>S : 1 digit</p> <p>S: Start R: Stop</p>

continued

Control	Command	Parameter
SCAN MODE	SM	1 to 4 : 1 digit 1: Scan Channel 2: Group Scan 3: Frequency Scan 4: Sweep
DATE	DT	10 digits: <u>Example: March 20, 1991</u> <u>1</u> <u>9</u> <u>9</u> <u>1</u> / <u>0</u> <u>3</u> / <u>2</u> <u>0</u> Year Month Day
TIME OF DAY	TI	8 digits: <u>Example: 13:25:30</u> <u>1</u> <u>3</u> / <u>2</u> <u>5</u> / <u>3</u> <u>0</u> Hour Minute Second
TIMER START & STOP	TS	S: :1 digit S: Start R: Stop
WAKE-UP TIMER	TM	1 to 4 : 1 digit 1: Timer 1 2: Timer 2 3: Timer 3 4: Timer 4
TIMER ON & OFF SETTING	TP	as desired
ATTENUATION ON & OFF	AT	S: :1 digit S: Receiver front end attenuator ON R: Receiver front end attenuator OFF
BAND	BA	1 : 1 digit 0: BAND 0 ? F: BAND 15
FILTER SETTING	FL	1 : 1 digit 0: FILTER 0 ? F: FILTER 15
SWITCH SETTING	SW	1 S : 2 digits 0S: SW 0 ON 0R: SW 0 OFF ? FS: SW 15 ON FR: SW 15 OFF

continued

FURUNO

Information

NO. : FQ 5-92-009 ^{1/3}

Date : 1992 - 4

Issued by : FURUNO ELECTRIC CO., LTD.
QUALITY ASSURANCE DEPARTMENT

Addenda No. 16 to Service Manual of FS-5000 SM-E5519

FS-5000/8000 Improvement of Duplex Communication

To reduce transmission noise in duplex communication, the EXC and RX boards have been modified for the sets having the serial numbers shown below. Refer to new schematic diagrams attached.


Model	Serial No.
FS-5000	2908-0225 to 0227, 0303 and after
FS-8000	2522-0041 and after

This modification improves duplex communication quality provided the receiving antenna is separated at least 5 meters from the transmitting antenna. (Of course, it is better to install the receiving antenna far away from the transmitting antenna.)

To reduce transmission noise, we recommend setting AGC and NB (Noise Blanker) to FAST and ON, respectively.


変更
MODIFIED

変更
MODIFIED



NOTE (1) Resistors are in Ω (0.1W). Capacitors are in F. Inductors are in H, unless otherwise noted.
 (2) Marks Δ are 1000pF/50WV capacitors. \triangle are 0.01 μ F/50WV capacitors and \square are 0.1 μ F/25WV capacitors.
 (3) Mark * R19, not provided for 05P0349A

主機種	FS-5000	コード		SHEET NO.	1/2
課長	検図	設計	製図	TITLE	
				1B02 (1/2)	
				EXC (TRANSCIVER UNIT)	
				C5519-K09-D	
				古野電気株式会社	



Note. 1) Marks 0 are 1000 PF 50WV Capacitors.
 2) Marks Δ are 0.01μF 50WV Capacitors.
 3) Marks Ⓜ are 0.1μF 25WV Capacitors.
 4) Resistors are in Ω (0.1w), Capacitors are in F, Inductors are in H, unless otherwise noted.

機種種	FS-5000	コード		SHEET NO.	1/2
課長	検	設計	製	TITLE	1B03 (1/2) RX (TRANSCIEVER UNIT)
				DWG. No.	C5519-K02-D

FURUNO

Information

NO. : FQ5-92-010

Date : 1992 - 4

Issued by : FURUNO ELECTRIC CO., LTD.
QUALITY ASSURANCE DEPARTMENT


Addenda No. 17 to Service Manual of FS-5000 SM-E5519

FS-5000/8000 Optional Supply of Connector Block Assembly (Terminal Board for power cable)

If the 14sq or 22sq power cable is used instead of the 8sq cable, it can not be connected to the power terminals, whose diameters are for 8sq cable, on the INTERFACE board in the transceiver unit.

To solve this problem, the connector block assembly is optionally supplied. The assembly mounts on the rear panel of the transceiver unit as shown below.

Name	Type	Code No.	Remarks
Connector Block Assembly	OP05-49	005-841-200	For FS-5000
	OP05-48	005-841-190	For FS-8000



FURUNO

Information

NO. : FQ5-92-011 ^{1/6}

Date : 1992 - 4

Issued by : FURUNO ELECTRIC CO., LTD.
QUALITY ASSURANCE DEPARTMENT

Addenda No. 18 to Service Manual of FS-5000 SM-E5519

FS-5000/8000 ROM Program Change (Ver. 10)

The program version of the ROMs on the control and transceiver units has been changed to "10" from March 1992.

Version 8 → 9

1. Contents of Modification

① Highest Priority of Distress Command ("DRS")

The "DRS" (Distress Set) command has the highest priority in the MIF data protocol.

The FS-5000/8000 accepts the "DRS" command from the DSC terminal to transmit a distress alert, even while transmitting.

② TX ON Command (TXS, TXR) added.

③ Frequency on DSC channel 9 amended. (5389kHz → 5380kHz)

Version 9 → 10

1. Contents of Modification

① Additional System Settings (See next page.)

([STO] → Channel No. → [ENT])

Channel No.	LCD Display	Description									
9947	SQ on Telex [0-Def, 1-OFF]	The "1" setting automatically turns off the SQ (if ON) when class of emission is changed to TELEX. (Note that AF signal to DP-5 is not passed through squelch circuit, so this setting is normally not necessary for DP-5 connection.)									
9948	NB on Telex [0-Def, 1-OFF]	The "1" setting automatically turns off the NB (if ON) when class of emission is changed to TELEX.									
9949	AGC on Telex [0-Def, 1-FAST]	The "1" setting sets AGC to FAST when class of emission is changed to TELEX.									
9950	Duplex on Telex [0-Def, 1-OFF]	The "1" setting inhibits DUPLEX mode (unnecessary on TELEX) when class of emission is changed to TELEX.									
9961	ITU Freq. Table [0-INT, 1-USA, 2-EU]	MF band ITU frequency list added. (at [2-EU] selection)									
9980	Country Code [44] (Enter numerals.)	Returns to default setting depending on country. See the next page.									
9981	Dummy Load [0-NO, 1-YES]	Determines the functions of both 9911 and 9923 as follows: <table border="1" style="margin-left: 20px;"> <thead> <tr> <th>9981</th> <th>[0] NO</th> <th>[1] YES</th> </tr> </thead> <tbody> <tr> <td>9911 : Alarm</td> <td>0-Receive</td> <td>1-Transmit</td> </tr> <tr> <td>9923 : Dummy</td> <td>1-Inhibit</td> <td>0-Enable</td> </tr> </tbody> </table>	9981	[0] NO	[1] YES	9911 : Alarm	0-Receive	1-Transmit	9923 : Dummy	1-Inhibit	0-Enable
9981	[0] NO	[1] YES									
9911 : Alarm	0-Receive	1-Transmit									
9923 : Dummy	1-Inhibit	0-Enable									
9982	A. BK relay or R. ANT [0-NO, 1-YES]	Determines the functions of both 9913 and 9917 as follows: <table border="1" style="margin-left: 20px;"> <thead> <tr> <th>9982</th> <th>[0] NO</th> <th>[1] YES</th> </tr> </thead> <tbody> <tr> <td>9913 : System Delay</td> <td>30ms</td> <td>10ms</td> </tr> <tr> <td>9917 : 50 ohm BK Relay</td> <td>0-on/off</td> <td>1-Permanently on (fixed)</td> </tr> </tbody> </table>	9982	[0] NO	[1] YES	9913 : System Delay	30ms	10ms	9917 : 50 ohm BK Relay	0-on/off	1-Permanently on (fixed)
9982	[0] NO	[1] YES									
9913 : System Delay	30ms	10ms									
9917 : 50 ohm BK Relay	0-on/off	1-Permanently on (fixed)									
9989	Power setting for [1-EU, 2-NOR]	Setting of power data. <u>"EU" (Europe)</u> <u>Power data</u> 1.6~2.5MHz : FS-5000 225 FS-8000 160 <u>"NOR" (Norway)</u> <u>Power data</u> 1.6~2.5MHz : FS-5000 only ... 200 2.5~4.0MHz : FS-5000 only ... 210 4.0~30 MHz : FS-5000 only ... 225									

Setting Number	Function	Default 0	Country Code					Result of selection
			Japan 81	USA 1	Europe 44	Norway 47	Holland 31	
9901	TX freq. selection	0				3		Marine
9903	TX o/p on MF band	0	2	1				50/150
9904	Class of emission on 2182 KHz	0		1				J3E
9907	Time display format	0		1	2	2	2	USA/EU
9910	Check meter numerics	0	1					
9913	System delay	30				10		
9917	50 ohm BK relay	0				1		on
9923	Dummy load	0	1	1	1	1	1	off
9926	Test tone	0		1	1	1	1	off
9927	Power reduction enable	0		1	1	1	1	2182
9928	Min o/p power	0		1	1	1	1	more than 60w
9947	SQ on TLX	0					1	off
9948	NB on TLX	0					1	off
9949	AGC FAST on TLX	0					1	FAST
9950	DUPLEX on TLX	0					1	Inhibit
9953	AM Operation	0		3	3	3	3	2182
9954	R3E Operation	0	1		1	1	1	RX
9955	FAX Operation	0	1		1	1	1	RX
9956	LSB Operation	0	1		1	1	1	RX
9961	ITU Freq. Table	0		1	2	2	2	USA/EU

Note: Where no data appears, default setting applies.

② Default Setting of System Delay for FS-8000 : 10ms

③ ITU Frequency Table and class of Emission

For previous software, if an operator changes class of emission after entering an ITU channel number, the channel did not change; only the class of emission changed. Now, the channel changes to the one corresponding to the class of emission selected.

(e.g.) Enter ITU401(SSB). → Change class of emission to TELEX. → Frequency changes to ITU4001.

④ Reduction ratio of power data is incorrectly published as decreasing in steps of 50.

55 is correct

<u>LCD display</u>	<u>Power data</u>	
Full	255	} -55
LOW1	200	
LOW2	145	} -55

⑤ MIF data (except for distress command “DRS” from DSC terminal) is ignored when both TX and RX frequencies are set at 2182kHz.

2. Factory Modification

Model	Serial Number
FS-5000	2508-0367 and after
FS-8000	2522-0046 and after

3. ROM Code Number

Type	Code No.
ROM05-501-31-110	005-927-440

MF BAND ITU TELEX FREQUENCY TABLE

Channel No.	Coast station (NBDP) (DSC) (kHz)	Ship station (NBDP) (DSC) (kHz)
201	1607	2142
202	1607.5	2142.5
203	1608	2143
204	1608.5	2143.5
205	1609	2144
206	1609.5	2144.5
207	1610	2145
208	1610.5	2145.5
209	1611	2146
210	1611.5	2146.5
211	1612	2147
212	1612.5	2147.5
213	1613	2148
214	1613.5	2148.5
215	1614	2149
216	1614.5	2149.5
217	1615	2150
218	1615.5	2150.5
219	1616	2151
220	1616.5	2151.5
221	1617	2152
222	1617.5	2152.5
223	1618	2153
224	1618.5	2153.5
225	1619	2154
226	1619.5	2154.5
227	1620	2155
228	1620.5	2155.5
229	1621	2156
230	1621.5	2156.5
231	1622	2157
232	1622.5	2157.5
233	1623	2158
234	1623.5	2158.5
235	1624	2159
236	1624.5	2159.5

MF BAND ITU SSB FREQUENCY TABLE

Channel No.	Coast station assigned frequency (kHz)	Ship station assigned frequency (kHz)	Channel No.	Coast station assigned frequency (kHz)	Ship station assigned frequency (kHz)
241	1636.4 (1635)	2061.4 (2060)	271	1726.4 (1725)	2070.4 (2069)
242	1639.4 (1638)	2064.4 (2063)	272	1729.4 (1728)	2073.4 (2072)
243	1642.4 (1641)	2067.4 (2066)	273	1732.4 (1731)	2076.4 (2075)
244	1645.4 (1644)	2070.4 (2069)	274	1735.4 (1734)	2079.4 (2078)
245	1648.4 (1647)	2073.4 (2072)	275	1738.4 (1737)	2082.4 (2081)
246	1651.4 (1650)	2076.4 (2075)	276	1741.4 (1740)	2085.4 (2084)
247	1654.4 (1653)	2079.4 (2078)	277	1744.4 (1743)	2088.4 (2087)
248	1657.4 (1656)	2082.4 (2081)	278	1747.4 (1746)	2091.4 (2090)
249	1660.4 (1659)	2085.4 (2084)	279	1750.4 (1749)	2094.4 (2093)
250	1663.4 (1662)	2088.4 (2087)	280	1753.4 (1752)	2097.4 (2096)
251	1666.4 (1665)	2091.4 (2090)	281	1756.4 (1755)	2100.4 (2099)
252	1669.4 (1668)	2094.4 (2093)	282	1759.4 (1758)	2103.4 (2102)
253	1672.4 (1671)	2097.4 (2096)	283	1762.4 (1761)	2106.4 (2105)
254	1675.4 (1674)	2100.4 (2099)	284	1765.4 (1764)	2109.4 (2108)
255	1678.4 (1677)	2103.4 (2102)	285	1768.4 (1767)	2112.4 (2111)
256	1681.4 (1680)	2106.4 (2105)	286	1771.4 (1770)	2115.4 (2114)
257	1684.4 (1683)	2109.4 (2108)	287	1774.4 (1773)	2118.4 (2117)
258	1687.4 (1686)	2112.4 (2111)	288	1777.4 (1776)	2121.4 (2120)
259	1690.4 (1689)	2115.4 (2114)	289	1780.4 (1779)	2124.4 (2123)
260	1693.4 (1692)	2118.4 (2117)	290	1783.4 (1782)	2127.4 (2126)
261	1696.4 (1695)	2121.4 (2120)	291	1786.4 (1785)	2130.4 (2129)
262	1699.4 (1698)	2124.4 (2123)	292	1789.4 (1788)	2133.4 (2132)
263	1702.4 (1701)	2127.4 (2126)	293	1792.4 (1791)	2136.4 (2135)
264	1705.4 (1704)	2130.4 (2129)	294	1795.4 (1794)	2139.4 (2138)
265	1708.4 (1707)	2133.4 (2132)	295	1798.4 (1797)	2061.4 (2060)
266	1711.4 (1710)	2136.4 (2135)			
267	1714.4 (1713)	2139.4 (2138)			
268	1717.4 (1716)	2061.4 (2060)			
269	1720.4 (1719)	2064.4 (2063)			
270	1723.4 (1722)	2067.4 (2066)			

(): CARRIER FREQUENCY

FURUNO

Information

NO. : FQ5-92-005 1/2

Date : 1992 - 4

Issued by : FURUNO ELECTRIC CO., LTD.
QUALITY ASSURANCE DEPARTMENT

Addenda No. 19 to Service Manual of FS-5000 SM-E5519.

FS-5000/8000 System Setting for Connection to NBDP

FS-5000

1. In case that a receiving antenna or ANT BK RELAY board is installed.

(1) System setting of FS-5000

50 ohm BK relay and TX delay time should be set to "ON" (fixed) and 10 ms, respectively.

STO 9982 ENT 1 ENT

(2) System setting of NBDP

① When DP-5 is connected ("Terminal" menu setting)

Slave Delay	:	4ms
BK Timing Pre tone	:	10ms
Post tone	:	0ms
Mute Timing Pre BK	:	0ms
Post BK	:	0ms

② When TT-1600 is connected

Receiver Post Mut	:	0×1.25ms
Transmitter Pre Key	:	8×1.25ms
Transmitter Post Key	:	0×1.25ms
Slave Delay	:	8×1.25ms

2. In case that 50 ohm BK relay is used.

- (1) System setting of FS-5000
50 ohm BK relay and TX delay time should be set to "ON/OFF" and 30 ms, respectively.

STO 9982 ENT 0 ENT

(2) System setting of NBDP

① When DP-5 is connected

[Slave Delay	:	30ms
	BK Timing Pre tone	:	30ms
	Post tone	:	0ms
	Mute Timing Pre BK	:	0ms
	Post BK	:	0ms

② When TT-1600 is connected

[Receiver Post Mute	:	0×1.25ms
	Transmitter Pre Key	:	24×1.25ms
	Transmitter Post Key	:	0×1.25ms
	Slave Delay	:	24×1.25ms

FS-8000

- (1) System setting of FS-8000
TX delay time should be set to 10ms.

STO 9913 ENT 10 ENT

(2) System setting of NBDP

① When DP-5 is connected ("Terminal" menu setting)

[Slave Delay	:	4ms
	BK Timing Pre tone	:	10ms
	Post tone	:	0ms
	Mute Timing Pre BK	:	0ms
	Post BK	:	0ms

② When TT-1600 is connected

[Receiver Post Mute	:	0×1.25ms
	Transmitter Pre Key	:	8×1.25ms
	Transmitter Post Key	:	0×1.25ms
	Slave Delay	:	8×1.25ms

FURUNO

Information

NO. : FQ5-92-013 1/7

Date : 1992 - 4

Issued by : FURUNO ELECTRIC CO., LTD.
QUALITY ASSURANCE DEPARTMENT


Addenda No. 20 to Service Manual of FS-5000 SM-E5519

FS-5000/8000 New Antenna Coupler

The Antenna Coupler AT-5000 has been modified to withstand a higher voltage on MF band (induced by a short antenna). Production of new coupler starts in May 1992. A heavy duty type stainless steel coupler is optionally available, for preventing icing, etc.

The following are the changes incorporated in the new coupler.

1. In the tuning circuit, voltage tolerance and capacitance of each element are remarkably increased. The COUPLER board is completely changed. Note that a new COUPLER board (05P0358-44) is interchangeable with a previous one (05P0358-33).
2. Antenna tuning sequence is changed. Refer to attached sheet.
3. A shortening capacitor and coupling capacitor (shunt capacitor) are automatically connected according to antenna length.
4. Memory device to store tuning data is changed from a RAM to a E²PROM, to store the data permanently.
5. CPU is changed. (ROM/RAM/AD converter incorporated)
6. DUMMY LOAD and ANT BK RELAY boards are modified to withstand a higher voltage. (Both boards can be used in a previous version antenna coupler; but both previous boards can not be used in a new coupler.)
7. Interconnection of COUPLER, DUMMY LOAD and ANT BK RELAY boards is changed.



8. Arrester gap is changed to 3mm.

9. Fixing method of coaxial cable is changed. (Two cable clamps are supplied.)

Types of New Antenna Coupler, Dummy Load PCB Assy. and Antenna BK Relay PCB Assy.


	New Antenna Coupler	Dummy Load PCB Assy.	Antenna BK Relay PCB Assy.
Type	AT-5000-H (Plastic)	OP05-34-H (for plastic antenna coupler)	OP05-35-H
	AT-5000-HS (Stainless Steel)	OP05-51-H...Note 1 (for stainless steel antenna coupler)	


Note 1: Fixing screws are different.


Factory Modification


Numbering of the new coupler begins from 1001.

Antenna Tuning Sequence










TUNE OK: Relay status retained. (Data is stored in E²PROM.) "TUNE OK" command is sent to transceiver unit.

TUNE ERROR: Tuning circuit is bypassed. "TUNE ERROR" command is sent to transceiver unit.

ANT BK RELAY Board (05P0359-11)


DUMMY LOAD Board (05P0360-11)



T Photo No.1257


COUPLER Board (05P0358-44)

New Antenna Coupler (AT-5000-H)



05E3-1812	4	4.3.16	ダミー+ANTBK配線経路変更	山本	x1
05E3-1775	3	3.12.9	C1, R1 削除	山本	x2
05E3-1601	2	2.5.10	C1, E1, R1 追加	山本	x3
05E3-1566	1	2.1.12	誤記訂正	家城	
変更通知書番号	符号	訂正年月日	訂正記事	担当	

機種種	FS-5000 FS-2500 FS-1600	コード		SHEET NO.	1/1
課長	89.10.11	設計	89.10.9	製図	89.10.9
図検	1.10.12	図	家城	図	家城
名	3B01 CHASSIS	分		番	05-001-3334-4
類	(COUPLER UNIT)	名			



NOTE (1) Resistors are in Ω (0.16W), Capacitors are in F, Inductors are in H, unless otherwise noted.
 (2) Mark Δ are 0.1μF/25V Capacitors and □ are 0.01μF/16V Capacitors with beads core.

CHECK RUN TEST

OSE3-1812	4.3.13	LED輝度検出回路の保護	山本	x4
OSE3-1775	3.12.2	新回	山本	
変更通知書番号	符号	訂正年月日	訂正記事	担当

主機種	FS-5000	コード		SHEET NO.	1/1
	FS-8000	型名			
課長	3.12.10	設計	3.11.30	分	
検図	山本	製図	山本	名	3B02 COUP
				図	05-001-3443-1

FURUNO

Information

NO. : FQ5-92-020

Date: 1992 - 7

Issued by: FURUNO ELECTRIC CO., LTD.
QUALITY ASSURANCE DEPARTMENT


Addenda No. 21 to Service Manual of FS-5000 SM-E5519

FS-5000/8000


Change of ALC Adjustment

FS-5000

Since the EXC board was modified in January 1992, ALC adjustment at factory has been changed as follows.



Please amend page 2-14 of the FS-5000 Service Manual.



Procedure


- 1.
2. Turn R9 ... indicates **240W**.
3. Adjust it for meter indication of **200W**.

Procedure

- 1.
2. Turn R9 ... indicates **190W**.
3. Adjust it for meter indication of **180W**.

FS-8000

R9 (ALC) on the EXC board is adjusted at factory as below.



Procedure

Adjust R9 for power meter indication of 360W.

FURUNO

Information

NO. : FQ5-92-025 1/2


Date: 1992 - 9

Issued by : FURUNO ELECTRIC CO., LTD.

Addenda No. 22 to Service Manual FS-5000 SM-E5519


FS-5000/8000 Optional R. ANT SEL Board

Some ships which use duplex communications may have a very long coax. cable for receiving antenna. This condition greatly lowers receiving sensitivity on MF band communications over modes other than duplex. To solve this problem, the R. ANT SEL Board is now optionally available.




Part	Type	Code No.
R. ANT SEL Board Assy	OP05-53	005-861-350

This board is installed next to the TX FIL Board inside the transceiver unit.




Transceiver Unit

The following accessories are supplied to connect the R. ANT SEL Board to the unit.



Interconnection


1. FS-5000



With ANT BK RELAY PCB (FOR TELEX COMMUNICATION)

*Cable ③ not necessary

2. FS-8000



FURUNO

Information

NO. : FQ5-92-034

Date : 1992 - 12

Issued by : FURUNO ELECTRIC CO., LTD.

TECHNICAL DOCUMENTATION SECTION

Addenda No. 23 to Service Manual FS-5000 SM-E5519



FS-1600/2500/5000/8000 ROM Program Change (Ver. 11)

Contents of Modification (Version 10 → 11)

1. Additional System Settings

Channel No.	Function	Setting			
		0	1	2	3
9916	Selection of [*] key function	not used	key lock	intercom call	—
9951	Receiving antenna on telex communication (Only when optional R ANT SEL board is installed.)	used	not used	—	—
9957	Cypher communication	disable	enable	—	—
9962	MF (405—526.5kHz) band for TX	not used	used (Note 1)	—	—
9963	User programming	enable	disable	—	—
9964	Check meter indication for both upper and lower transceiver units (FS-8000 only)	no	yes	—	—



Factory Setting

Note 1: Optional antenna coupler AT-410 (under development) is required.

2. Intercom function added.

(Set channel 9916 to "2" to use the [*] key for intercom call.)

Note that the AF board 05P0356-33 in the Control Unit is required.

(This board is under development.)

3. Low power data changed.

	MF band	HF band
FS-5000	100 ⇔ 115	100 ⇔ 110
FS-8000	70 ⇔ 90	70 ⇔ 75

4. TX tuning error indication added.

Error indication "TX TUNE is off" appears when [TX TUNE] key is pressed with system setting 9905 ([TX TUNE] key function) set to "OFF".

Modified Sets

From the production in November 1992.

ROM Code Number

Type: PROM 0550131111

Code No.: 005-927-440

FURUNO

Information

NO. : FQ5-93-001 ^{1/2}Date: 1993 - 02Issued by : FURUNO ELECTRIC CO., LTD.
TECHNICAL DOCUMENTATION SECTION

Addenda No. 24 to Service Manual of FS-5000 SM-E5519

M. Med.

FS-5000/8000 ROM PROGRAM CHANGE

The program of the ROMs (three) in the Control Unit, Transceiver Unit and Antenna Coupler has been changed as follows from the production of February 1992.

Unit	Control	Transceiver	Antenna Coupler
ROM Version No.	1.12 (CPU board)	Same as left.	1.02 (COUPLER board)
Program No.	05-501-31-112		05-501-54-102
Code No.	005-927-440-00		005-860-330-00

Modification

ROMs for Control and Transceiver Units (Ver. 1.12)

- (1) When the circuit of the EXC board (05P0349) was changed to "suffix-33" in January 1992 to reduce transmission noise on duplex communication (refer to Furuno Information FQ5-92-009 issued in April 1992), tuning power of the FS-8000 was reduced, which caused tuning error. To resolve this problem, the tuning power of the FS-8000 has been increased.
- (2) A terminal board on the INTERFACE board (05P0354) was newly added for detection of the AC mains failure in December 1992. For the sets produced in December 1992 and after (incl. RC-5000/8000 series):
 1. The software bug, that the output power is not always reduced automatically when AC mains cuts off, has been removed. (RC-5000/8000 series only)
 2. Automatic power reduction data (power data) when AC mains fails can be adjusted as shown below.
 - [STO] → [LOW] → press and hold [LOW] or [FULL] → [ENT]

(For previous ROM, the above data was determined by maximum power data setting.)

- (3) The minimum output power, when system setting 9928 ([STO] 9928) is set to "1" (60W or higher), is increased to get 60W power securely.

When you select system setting 9928 to "1", the minimum power data is automatically set as below, and the maximum power data is preset to the default setting ("255").

Model	Minimum Power Data
FS-5000	MF: 115, HF: 110
FS-8000	MF: 90, HF: 85

- (4) For system setting 9980, when "31" (Netherlands) is entered, system setting 9901 is automatically set to "3" (Marine free).


ROM for Antenna Coupler (Ver. 1.02)

- (1) The software bug described below has been removed.

The "Tuning error" occurs on the frequency higher than 3.36 MHz. This is because the pi-network tuning sequence is skipped (software bug) if the gamma-network cannot be tuned.

How to remove ROM on the COUPLER board

Using a slotted-head screwdriver (blade width 3mm or less), remove ROM by inserting it into "clearance" between ROM and socket as shown below. (Piano wire may be used instead of a screwdriver.)



Relationship between Model & ROM to be replaced

Model	ROM to be replaced
RC-5000/8000 series	All ROMs (Three ROMs)
FS-8000 in which tuning error occurs.	
FS-5000 in which tuning error occurs.	ROM in the antenna coupler only.

FURUNO

Information

NO. : FQ5-93-012

Date : 1993 - 04

Issued by : FURUNO ELECTRIC CO., LTD.
TECHNICAL DOCUMENTATION SECTION

Addenda No. 25 to Service Manual of FS-5000 SM-E5519



FS-5000/8000

1. Protection of PA Transistors 2. Installation of ANTENNA EARTH RELAY Board (for Grounding TX Antenna)

1. Protection of PA Transistors (Overcurrent protection: max. 21A)

Excessive current may flow into the PA transistors momentarily when the matching status between an antenna and a coupler changes, damaging the transistors. To solve this problem, the PA CHECK board has been changed from 12/92. (The new PA CHECK board (05P0367-22) detects current flowing into the PA transistors and delivers its output to the ALC circuit of the EXC board.)

The next page shows how to mount and adjust the new PA CHECK board locally. This modification can be done for the sets having suffix number shown below. (Production in 11/92 and earlier)

{ INTERFACE board: 05P0354-11
INTERFACE board: 05P0362-11 (FS-8000)
PA CHECK board: 05P0367-11 }

2. Installation of ANTENNA EARTH RELAY Board

To connect a transmission antenna to ground automatically while the unit is not transmitting, install the ANTENNA EARTH RELAY board in the antenna coupler. This protects the transmission circuit against lightning when the 50 ohm BK relay in the TX FIL board is turned on, that is, the transmission circuit is connected to the antenna. The procedure for installation is on page 6/8.

Applicable equipment: Units using new antenna coupler
(Serial No. 1001 and after)

Modification for protection of PA transistors (For FS-5000)

	<u>Qty</u>
Necessary Parts: 1. New PA CHECK Board.....	1
2. PH Connector Assy. (2P-10P)	1
3. Carbon Resistor (680, 1/6W)	1

Procedure

Before replacing the PA CHECK board, measure the I_c current, using the existing PA CHECK board.

Conditions

Frequency : 4MHz (SSB)

Output Power : LOW1

Tone : Single tone

[STO] [9926] [ENT] [0] [ENT]

I_c Indication : ON

[STO] [9910] [ENT] [1] [ENT]

1. Turn off the power and replace the PA CHECK board with new one.
2. Turn on the power and measure the I_c current using the same conditions mentioned above.
3. Compare both values of I_c . If they are not the same, adjust R4 on the new PA CHECK board for coincidence.
4. Turn off the power and connect a PH connector assembly between J4 on the PA CHECK board and J9 (ALC terminal) on the INTERFACE board.
5. Change resistance value of R146 on the EXC board from 3.3k ohms to 560 ohms by inserting a 680 ohm resistor in parallel with R146.
6. Turn on the power, set the output power to FULL and transmit by single tone (SSB) on all bands.
7. Confirm that I_c indication does not exceeds 21A on all bands. If it exceeds 21A, adjust R35 (clockwise) on the PA CHECK board.
8. Restore "Tone" and " I_c Indication" system settings to previous settings.

Modification for protection of PA transistors (For FS-8000)

	<u>Qty</u>
Necessary Parts: 1. New PA CHECK Board.....	2
2. PH Connector Assy. (2P-10P)	2
3. PH Connector Assy. (10P-).....	2
4. Carbon Resistor (680, 1/6W)	1
5. ROM (Ver. 1.11 or 1.12)	2

Procedure

1. Replace ROMs on the CPU board in the control unit and transceiver unit with new ones.
(Ver 1.11 or 1.12)
2. Turn on the power and change the system setting **9964** as shown below, to display respective Ic indication of the upper and lower units.

[STO] [9964] [ENT] [1] [ENT]

3. Before replacing the two PA CHECK boards, measure Ic current of both the upper and lower units using the existing PA CHECK board.

Conditions

Frequency :4MHz (SSB)


Output Power :LOW 1

Tone : Single tone


[STO] [9926] [ENT] [0] [ENT]

Ic Indication : ON


[STO] [9910] [ENT] [1] [ENT]



4. Turn off the power and replace the PA CHECK boards with new ones.
5. Turn on the power and measure the I_c current of both the upper and lower units using the same conditions mentioned earlier.



6. Compare values of (A) and (C). If they are not the same, adjust R4 on the new PA CHECK board in the lower unit.
7. Adjust R4 on the new PA CHECK board in the upper unit if the values of (B) and (D) are not the same.
8. Turn off the power and solder two flying wires from a PH connector assembly (10P-) to J9 on the INTERFACE boards (05P0354 and 05P0362) as shown below.



9. Connect a PH Connector assembly (2P-10P) between J4 on the PA CHECK board and 10P connector from the INTERFACE board (05P0354) in the lower unit, and between J4 on the PA CHECK board and 10P connector from the INTERFACE board (05P0362) in the upper unit.

10. Change resistance value of R146 on the EXC board from 3.3k ohms to 560 ohms by inserting a 680 ohm resistor in parallel with R146.
11. Turn on the power, set the output power to FULL and transmit by single tone (SSB) on all bands.
12. Confirm that Ic indication does not exceed 21A on all bands (for both lower and upper units). If it exceeds 21A, adjust R35 (clockwise) on the PA CHECK board.
13. Restore the system settings to the previous settings.

Mounting ANTENNA EARTH RELAY PCB on Antenna Coupler (New Coupler)

Necessary Parts:	Q'ty
① ANTENNA EARTH RELAY PCB (05P0578, with cables)	1
② Spacer for mounting ANT BK RELAY PCB	5
③ CK clamp (CK-05H)	1
④ Panhead screw B (M3 × 10)	5

Procedure

1. Mount the board on the COUPLER board by using screws and spacers (if necessary).



Without ANT BK RELAY PCB

With ANT BK RELAY PCB

2. Change wire connections as shown below.

DUMMY
LOAD PCB

J2 ← ANT output terminal
J4 ← J4 on COUP PCB



DUMMY
LOAD PCB

J2

ANT. EARTH
RELAY PCB

Connector

Connector

ANT
output terminal

J4

Connector


Connector

J4 on
COUP PCB


(*) Connect ground wire as shown on the next page.

Previous

New



Previous



New

Operation: When the DUMMY key is on or the power is turned off, a transmission antenna is automatically connected to ground to protect the transmission circuit in the transceiver unit against lightning.

Information


No. : FQ5-93-016Date : 1993 - 05Issued by: **FURUNO ELECTRIC CO., LTD.**
TECHNICAL DOCUMENTATION SECTION

Addenda No.26 to
FS-5000 SM-E5519.
Addenda No.3 to
FS-8000 SM-E5521.
Addenda No.2 to
DSC-5 SM-E5522.

FS-5000/8000 series, DSC-5 **Remedy for Key Lock up**

M. Mochizuki

The keyboard of the FS-5000/8000 and/or the SCAN key of the DSC-5 may lock when equipment is connected as shown in the figure below.



Symptom

The keyboard of the FS-5000/8000 and/or the SCAN key of the DSC-5 may lock when the AA-50 detects a dot pattern while the FS-5000/8000 scans the DSC frequency through the DSC-5 (preselector: ON).

(To restart operation, turn the power switch or the breaker off and turn it on again.)

Cause

Software bug.

Local Remedy

Replace three ROMs.

Name	Type	Code no.	Qty
FS-5000	05501-31-113 (Ver. 13)	005-927-440-02	2
DSC-5	05501-39-115 (Ver. 15)	005-996-140-02	1



Contents of ROM Change

Refer to the following Furuno Information.

- FS-5000/8000 ROM Program Change
- DSC-5 ROM Program Change

Urgency

Immediately replace ROMs when returning to port.

Factory Modification

From the production in May 1993.

Factory Modification From the production in May 1993.

Urgency Replace ROM immediately in case of item (1).

Program Number 05501-31-113

Code Number 005-927-440-02

Remarks For the RC-5000/8000 radio console sets having ROM version number 11 or earlier, adjust automatic power reduction data (minimum power data) after replacing ROM, referring to Furuno Information FQ5-93-001 issued in March 1993.

Applicable Operator's Manual for Version No. 13:
OM-E5519-0K (FS-5000)
OM-E5521-0F (FS-8000)

Addenda No. 27 to FS-5000 SM-E5519

Addenda No. 4 to FS-8000 SM-E5521

**FS-5000/8000
ROM PROGRAM CHANGE (Ver. 13)****Contents of
ROM Change**

(1) In the series connections of the DSC-5/AA-50/FS-5000 (8000), the keyboard of the FS-5000 may lock when the FS-5000 scans the DSC frequency through the DSC-5 with the PRESELECTOR key turned on. This software bug has been removed.

(2) System setting 9952 is added.

[STO]→ [9952]→ Tx antenna status at reception

{ 0: OFF (No change)→Default
1: ON (Connected to GND)· (*1) }

(*1) This function is available only when the Rx antenna is installed and dummy load board with antenna earth relay is mounted in the coupler.

If you want to connect the Tx antenna to ground manually (irrespective of 9952 setting), press the [DUMMY] key. (For HF band of the FS-8000, this function is operative only when the output power is selected for "Low2" or less.)

(3) Tuning is automatically done when pressing the PTT switch after turning on or off the [DUMMY] key.

(4) If sensitivity setting is less than "7", the AGC and sensitivity settings are automatically changed to "ON" and "maximum", respectively when the [2182] or [2187.5] key is pressed or the "DR" command from other equipment is received.

(5) System setting 9951 is amended as below.

<u>Incorrect</u>	<u>Correct</u>
[0: YES , 1: NO]	[0: NO, 1: YES]

Shading shows default setting.

ROM Replacement


FS-5000/8000

1. Replace the ROMs on the CPU board in the Control and the Transceiver Units with new ones.

DSC-5

(Clearing EEPROM is required.)

1. Replace the ROM on the Control board.
2. Turn the power on. The following screen appears.



3. Press **SELECT** twice to advance the cursor to "EEPROM."
4. To print out the contents of the EEPROM, press **0**. The ship's ID number, "COMM" setting, etc. will be printed.
5. Press **ENT** to clear the contents of the EEPROM.
6. Restore the system settings as they were before.

Addenda No. 28 to Service Manual FS-5000 SM-E5519
 Addenda No. 5 to Service Manual FS-8000 SM-E5521




FS-5000/8000 SSB RADIOTELEPHONE New Version AF Board (-33)

The FS-5000/8000 will have a new version AF Board from the production in August 1993. The new version no. is 05P0356-33. This technical information describes the changes made to this board.

Changes

Connection of Remote Station RB-500

- 1) The new version AF Board has terminals for current loop. They are on the REM2 terminal and are connected as follows.




The new version AF Board has the terminals for current loop (TB4 #1-#4). Because of the addition of those terminals, the terminals for connection of CIF/NMEA will be changed from TB4 #1-#4 to #7-#10.

You set the data format of equipment connected to the REM2 by jumper wire, as shown in the table below.

Jumper Wire (see drawing on page 4/6)	Format
Short	Current Loop
Open (factory setting)	RS-232C

- 2) As shown in the illustration on the previous page, +12 V power for the RB-500 is taken from the #5 terminal of TB4. (Currently +18 V is taken from the #9 terminal of TB1 and a resistor is inserted on the RB-500 to lower voltage to +12 V.)

As the result the new version AF Board is connected to the RB-500 as follows.



- 3) Squelch function will be available at the RB-500. (Currently the AF signal comes to the line output (AF RX) terminal on the FS-5000 without passing through the squelch circuit. In the new version AF board it passes through the squelch circuit.)

Intercom function available with RB-500 connection

The intercom function was added to the FS-5000 in November 1992, by ROM version 1.11. No hardware was available at that time; however, the new version AF Board has an intercom circuit. You can enable the intercom function by pressing the following keys


[STO] [9916] [ENT] [2] [ENT]

You operate the intercom function on the front panel by using [*], [ENT], [CLEAR] keys.

- Calling: [*], (terminal no.), [ENT], then communicate
- Ending communications: [CLEAR]
- Answering: [ENT], then communicate

Potentiometer for adjustment of MIC gain

A potentiometer for adjustment of MIC gain (R5: MIC GAIN) is added. Adjust it when MIC gain is too high.



05E3-1741	3.9.26	7+1+1+1+1+1+1+1+1	追加の部品を確保	追加
05E3-1546	2.10.19	4+1+1+1+1+1+1+1+1	4+1+1+1+1+1+1+1+1	追加
05E3-1585	2.3.8	Tx Freq 改定 4.10.30	追加	追加
05E3-1566	2.1.12	Rx Freq 改定 4.1.10	追加	追加
05E3-1559	1.11.6	記録修正 CIP/NMEA 切替	追加	追加
変更通知番号	符号	訂正年月日	訂正記号	担当

NOTE (1) Resistors are in Ω (0.1W). Capacitors are in F. Inductors are in H, unless otherwise noted. (2) Marks ○ are 1000pF/50WV capacitors. △ are 0.01μF/50WV capacitors and □ are 0.1μF/25WV capacitors.

機種	FS-5000	コード		SHEET	1/1
型名				NO.	
課長	1/10/12	設計	6/12/15	分類	2B03
検図	1/10/12	製図	6/12/15	名称	AF (CONTROLLER UNIT)
分		名		図番	05-001-3333-9

Addenda No. 29 to
FS-5000 SM-E5519
Addenda No. 6 to
FS-8000 SM-E5521

M. Mada

FS-5000/8000 Remedy for Garbled Audio

Symptom

Your partner cannot hear your voice clearly.


Cause

Low level audio is cut off by CR21 and CR22 on the EXC board (05P0349-33), which were added for noise reduction (reduction of interference from own transmitter to receiver) on duplex communication, in January 1992.

Field remedy

(1) Note white noise level by pressing PTT switch on duplex mode; (2) **Add a resistor** (R155: 150 ohms, 1/6W, 000-329-017) in parallel with CR21 and CR22 on the EXC board, and (3) Compare the level of white noise with that of before modification.

White noise should increase slightly. If necessary, adjust resistance of R155; the higher the resistance (max. 220 ohms), the lower the level of the white noise on the duplex mode but the worse the clarification.



Urgency

Tick	Action
	Immediately (ask ship's captain to remedy if the ship is out)
	As soon as the ship returns to port
	When it is convenient
✓	When symptom occurs

Factory modification

From the production in July 1993.

Remarks

If the duplex mode is not used, short CR21 and CR22 to clarify voice.

Addenda No. 30 to
FS-5000 SM-E5519
Addenda No. 7 to
FS-8000 SM-E5521**FS-5000 Series**
ROM Program Changes (Ver. 15)**Changes made
to ROM program**

- The following problems were eliminated.
 1. Frequency cannot be set 30 seconds to one minute after turning on the power and the error message "Tx frequency unlock" appears.
 2. Telex communication errors; NBDP terminal DP-5 cannot receive message completely, or connection is broken.

- The factory settings of the system channels were changed as follows.

System CH	Function	Factory Setting
9947	Squelch in telex mode	1 (OFF)
9948	Noise blanker in telex mode	1 (OFF)
9949	AGC in telex mode	1 (FAST)
9965	Scan response time	1 (FAST)

Program number

PROM0550131115

**Note for replacement of ROM
in the field**

After replacing the ROM, display the system channels and set them as shown in above table.
setting procedure (key operation)

[STO] [9] [9] [] [] [ENT] [] [ENT]

|
 system channel setting

**Factory
modification**

From the production in July 1993.

Remarks

The ROM program version number of the DP-5 is now 2.00. (It eliminates Telex Communication problems.)
We recommend that the DP-5 having new ROM (ver. 2.00) be used with FS-5000 series.

Addenda No. 31 to FS-5000
Service Manual SM-E5519Addenda No. 8 to FS-8000
Service Manual SM-E5521*M. Meads*

FS-5000/8000

ROM Program Changes (Ver. 17)

Changes made to ROM program

System setting 9966 is added so as to determine whether the transmission of two-tone alarm is restricted or not.

Procedure: [STO] → **9966** → [ENT]



In accordance with both the above setting and system setting 9953 (Operation on AM mode), the transmission of two-tone alarm on AM mode is as follows:

System setting 9966 Setting No.	System setting 9953 Setting No.	TX of two-tone alarm on AM mode
0 (FREE) (Factory setting)	0 (TX/RX)	Possible on all frequencies.
	1 (RX only)	
	2 (No)	Disabled
	3 (2182)	Possible on all frequencies.
1 (LIMITED)	0 (TX/RX)	Possible on all frequencies.
	1 (RX only)	Disabled
	2 (No)	
	3 (2182)	Possible on 2182 kHz only.



Program number PROM 0550131117

Code number 005-927-440

Factory modification From the production in Feb. 1994

Remarks The version no. of the ROM on the COUPLER board in the antenna coupler will be changed from 03 to 05 in April 1994 (Minor change). However, ROM version no. 3 remains compatible with the transceiver unit having ROM version no. 17.

Addenda No.32 to FS-5000 Service Manual SM-E5519
Addenda No.9 to FS-8000 Service Manual SM-E5521

FS-5000/8000 New Software (V. 21)

The Convention and the International Regulations were changed and H3E 2182 kHz watch receiver need not be fitted on board a ship after full implementation of GMDSS. Now 2182 kHz is transmitted only on J3E.

According to this change, the software for the FS-5000 was changed as follows.

New software: 05-501-31-121

Factory-modified sets

FS-5000 (Control Unit): 2508-1979 and after
FS-5000T: 3423 and after
FS-8000: From the next production

Changes to be made

- 1) System channel 9904 (Emission mode on 2182 kHz): "2:J3E FIX" is added.
- 2) System channel 9923 (Dummy): Default is changed to 1: Prohibited.
- 3) System channel 9953 (AM operation): Default is changed to 0: TX/RX for Japan and 1: RX for other countries.
- 4) System channel 9966 (Two-tone alarm TX): "2: TX prohibited" is added. Default is 0: Free for all countries. If "2: TX prohibited" is selected, regardless of 9953 setting, two-tone alarm is not emitted.
- 5) Two-tone alarm test with dummy load functions as follows.
With system channel 9911 set to 1: TX, emission mode depends on the setting on 9904, and output power is Full on H3E and Low-1 on J3E.
- 6) GGA (NMEA sentence) is receivable.
- 7) With 9937 to 9939 (emission mode of TX for REMOTE) set to other than 0: No change, every time after transmission on an ITU channel by the TX KEY, tuning is made. This problem is solved.
- 8) With 9937 to 9939 (emission mode of TX for REMOTE) set to 1: AM, TX cannot be stopped by setting TX KEY to OFF if 9953 is set to other than 1. This problem is solved.
- 9) RX self-test (9914) sometimes ends with NG if AGC is set to SLOW in CW and AM modes. This problem is solved.
- 10) With system channel 9949 set to 1: FAST, AGC remains FAST when the mode is changed from TELEX to SSB. This problem is solved.
- 11) Default of MF power data (FS-2500) is changed to 200 and its upper limit to 255.

⑤

SSB

Information

Issued by: **FURUNO ELECTRIC CO., LTD**

APPROVED BY *[Signature]*

SERVICE MANAGEMENT & COMMANDING DEPARTMENT

WRITTEN BY *[Signature]*

Addenda No. 33 to FS-5000 service manual, Pub. No. SME-5519

Addenda No. 10 to FS-8000 service manual, Pub. No. SME-5521

FS-5000/8000 New CPU/EXC/RX Boards

Urgency: When servicing

Three printed circuit boards, CPU, EXC, and RX are modified because the production of PLL IC, M54927P is discontinued. New CPU board recognizes EXC and RX board type, so new CPU board is used with old EXC and/or RX board without modification.

Table 1 lists type and code number of new boards and table 2 shows the compatibility between old and new boards.

Table 1 New p.c. boards

Board name	Type	Code number	Usage
CPU board	05P0347A	005521030	FS-5000T/8000T
RX board	05P0348A	005521140	FS-5000T/8000T
EXC board	05P0349B	005521160	FS-5000T
EXC board	05P0349C	005521170	FS-8000T

⑤

SSB

Table 2 Compatibility between old and new p.c. boards

Board		New transceiver	Old transceiver	Usage
New CPU	05P0347A	X	X	FS-5000T FS-8000T
Old CPU	05P0347	N.A	X	
New RX	05P0348A	X	See next page.	FS-5000T FS-8000T
Old RX	05P0348	X	X	
New EXC	05P0349B	X	See next page.	FS-5000T
Old EXC	05P0349-Z	X	X	
New EXC	05P0349C	X	See next page.	FS-8000T
Old EXC	05P0349A-Z	X	X	

Factory-modified sets

FS-2500T/5000T: 2990, 2994, and after

FS-8000T: 0279, and after

How to use new board in old transceiver

To use new EXC and/or RX board in the old transceiver, follow the procedure below.

1. Change CPU board to new one.
2. Change PROM in FS-5000C to Ver. 0550131124.
3. Change EXC and/or RX board with new one.
4. Connect new CPU board with new EXC (RX) board.

J7 (4P) on CPU board (05P0347A) <<<<>>>> J10 (4P) on EXC board (05P0348B/C)
 J8 (5P) on CPU board (05P0347A) <<<<>>>> J10 (5P) on RX board (05P0348A)

Necessary parts

Parts name	Type	Code number	Remarks
PH connector assy.	PH04DK-320	000149706	RX/CPU
PH connector assy.	PH05DK-400	000149707	EXC/CPU
PROM	05501311 <u>24</u>	00592744005	For FS-5000C




Fig.1

Automatic board recognition

Board type signal, or "p.c.b type" signal is connected to EXC and RX boards as shown in Fig. 2. The CPU sets the signal to both L and H levels and if the CPU detects the set level, the board is new.





Fig. 2 "p.c.b type" signal lines on EXC and RX boards


Difference between 05P0349B and 05P0349C

The EXC board for FS-5000, 05P0349B has a 50-ohm terminator at OUT-2 port, but one for FS-8000, 05P0349C does not. With the FS-5000, the PA is connected to OUT-1 port.




NOTE
Marks * are options.

DRAWN 04/03/03 T. YAMASAKI	FS-1600	TYPE FS-500T
CHECKED 04/03/03 T. Takano	FS-2500	名称 送受信部 (総合)
APPROVED 04/03/11 H. Idagawa	FS-5000	回路図
SCALE MASS	MODEL BLOCK No.	NAME TRANSCEIVER UNIT (GENERAL)
Dwg No. C5519-K12-E	05-001-3322-8	SCHEMATIC DIAGRAM




NOTE
Marks ※ are options.

DRAWN 04/03/03 T. YAMASAKI	TYPE FS-8000T (1/2)
CHECKED 04/03/04 T. YAMASAKI	名称 送受信部 (下部)
APPROVED 04/03/11 H. ITOYAMA	回路図
SCALE MASS	MODEL FS-8000
Dwg No. C5521-K03-C	BLOCK No. 1B 01
	NAME TRANSCEIVER UNIT (LOWER)
	SCHMATIC DIAGRAM




NOTE (1) Resistors are in Ω (0.1W). Capacitors are in F. Inductors are in μ H, unless otherwise noted.
 (2) Marks \square are 100PF/50WV capacitors. Δ are 0.01 μ F/50WV capacitors and \square are 0.1 μ F/25WV capacitors.
 (3) Mark * R19 not provided for 05P0349A

DRAWN 04/03/03 T. YAMASAKI	TYPE 05P0349B/C (1/2)
CHECKED 04/03/04 T. YAMASAKI	名称 EXC 基板
APPROVED 04/03/04 T. YAMASAKI	回路図
SCALE MASS	NAME EXC PCB
Dwg No. C5519-K09-G	MODEL BLOCK No. 1B 02
	05-001-3323-15
	SCHEMATIC DIAGRAM




NOTE (1) Resistors are in Ω (0.1W), Capacitors are in F.
 Inductors are in H, unless otherwise noted.
 (2) Marks ○ are 1000pF/50WV capacitors.
 △ are 0.01μF/50WV capacitors and
 □ are 0.1μF/25WV capacitors.

DRAWN 04/03/03 T. YAMASAKI	TYPE 05P0349B/C (1/2)
CHECKED 14/03/04 T. Takano	名称 EXC (SYN) 基板
APPROVED 04/03/11 14. Hayashi	回路図
SCALE MASS	FS-5000T 1B 02
MODEL BLOCK No.	NAME EXC(SYN) PCB
Dwg No. C5519-K10-G	SCHEMATIC DIAGRAM




Note
 1) Marks ○ are 1000pF/50WV Capacitors.
 2) Marks △ are 0.01μF/50WV Capacitors.
 3) Marks □ are 0.01μF/50WV Capacitors.

DRAWN 04/03/03 T. YAMASAKI CHECKED 04/03/04 T. Takano APPROVED 04/03/11 M. Suganoh SCALE MASS	TYPE 05P0348A (1/2) 名称 RX 基板 回路図 RX PCB SCHEMATIC DIAGRAM
Dwg No. C5519-K02-F	MODEL FS-500T 1B 03 BLOCK No. 05-001-3324-16



DRAWN 04/03/03 T. YAMASAKI	TYPE 05P0348A (2/2)
CHECKED 04/03/04 T. Takai	名称 RX (SYN) 基板
APPROVED 04/03/11 H. Hayashi	回路図
SCALE MASS	FS-5000T 1B 03
Dwg No. C5519-K03-F	MODEL BLOCK No. NAME 05-001-3324-4 RX(SYN) PCB
	SCHEMATIC DIAGRAM

1B04 CPU
05P0347A



NOTE (1) Resistors are in Ω , Capacitors are in F and inductors are in H unless otherwise noted.
 (2) VDD and GND pin location.
 VDD-14 GND-7 VDD-16 GND-8
 TC74HC04 TC74HC138
 TC74HC32 TC74HC238
 TC74HC86

DRAWN 04/03/03 T. YAMASAKI	TYPE 05P0347A
CHECKED <i>[Signature]</i>	名称 CPU 基板
APPROVED <i>[Signature]</i>	回路図
SCALE MASS	MODEL BLOCK No.
Dwg No. C5519-K08-D	NAME CPU PCB
05-001-3325-2	SCHEMATIC DIAGRAM