


ALL BAND SWITCHES SHOWN IN POSITION 5

REVISED	EXPLANATION	DATE
A	Change in location of 53 pin	11/15/52
A	Lead on 115V tap removed	"
A	Changed as indicated	"
A	Moved from top of winding	"
A	Emphasizing spk. leads	"
A	Removed the spk. leads on 115V & 115K taps. THE CHANGE REMOVED FROM DRAWING	"
C	REV. R METER WIRING	"
C	REWORKING OF NOTE SILENCER	"



XTAL FILTER PLUG IN UNIT